

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

Not available

The Motor Claims Dept.

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

SHD7305J

not available
2/s #5000
5 days
19/4/21
highlighted items

ESTIMATE

DATE : 19/04/2021

VEHICLE NO : SJV694M

MAKE/MODEL : TOYOTA VIOS

ACC DATE : 17/04/2021

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
	<u>LIST PRICE</u>		
1	1 REAR BOOT <i>3rd/3rd</i>	\$ 665.90	\$ 665.90 ✓
2	2 REAR BOOT HINGE RH / LH <i>17</i>	\$ 68.50	\$ 137.00 X
3	1 REAR BOOT RUBBER <i>Torn</i>	\$ 162.84	\$ 162.84 ✓
4	1 REAR BOOT LOCK <i>159.10</i>	\$ 289.50	\$ 289.50 ✓
5	1 REAR BOOT LOCK CATCH <i>17</i>	\$ 48.85	\$ 48.85 X
6	1 REAR BOOT EMBLEM LOGO <i>new</i>	\$ 42.60	\$ 42.60 ✓
7	1 REAR BOOT EMBLEM VIOS <i>new</i>	\$ 48.85	\$ 48.85 ✓
8	1 REAR BOOT EMBLEM E <i>new</i>	\$ 30.94	\$ 30.94 ✓
9	2 REAR TAILLAMP RH / LH <i>one new</i>	\$ 481.65	\$ 963.30 ✓
10	2 REAR TAILLAMP PANEL HOUSING	\$ 105.00	\$ 210.00 X
11	1 REAR BUMPER <i>DIS</i>	\$ 459.75	\$ 459.75 ✓
12	2 REAR BUMPER REFLECTOR RH / LH <i>one</i>	\$ 106.25	\$ 212.50 ✓
13	2 REAR BUMPER BRACKET RH / LH <i>17</i>	\$ 95.50	\$ 191.00 X
14	2 REAR BUMPER SIDE HOLDER RH / LH <i>3rd</i>	\$ 82.50	\$ 165.00 ✓
15	2 REAR BUMPER SIDE RETAINER RH / LH <i>3rd</i>	\$ 89.65	\$ 179.30 ✓
16	1 REAR EXHAUST BOX <i>2</i>	\$ 569.05	\$ 569.05 X
17	2 REAR EXHAUST MOUNTING <i>17</i>	\$ 42.50	\$ 85.00 X
18	1 REAR END PANEL <i>body</i>	\$ 777.25	\$ 777.25 ✓
19	1 REAR END PANEL GARNISH <i>one</i>	\$ 89.65	\$ 89.65 ✓
20	1 REAR SPARE TYRE PANEL <i>R</i>	\$ 781.65	\$ 781.65 X
21	2 REAR SPARE TYRE PANEL TOOL FOAM RH / LH <i>2nd/2nd</i>	\$ 126.20	\$ 252.40 ✓
22	1 REAR SPARE TYRE PANEL TOOL FOAM - CENTER <i>17</i>	\$ 105.00	\$ 105.00 X
23	1 REAR SPARE TYRE PANEL CARDBOARD <i>7/11</i>	\$ 156.50	\$ 156.50 ✓
24	1 REAR SPARE TYRE SCREW CARRIER <i>17</i>	\$ 39.20	\$ 39.20 X
25	2 REAR FENDER INNER TRIM RH / LH <i>17</i>	\$ 286.50	\$ 573.00 X
26	2 REAR FENDER LOWER SHIELD RH / LH <i>17</i>	\$ 58.50	\$ 117.00 X
			\$ 7,353.03
		LESS - 25%	\$ 1,838.26
		TOTAL <i>5026</i>	\$ 5,514.77

T K LEE AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
<u>SPECIAL NETTS ITEM</u>			
1	1SET REAR BUMPER REVERSE SENSOR <i>one</i>	\$	280.00 <i>200</i>
2	1 REAR BUMPER SPOILER <i>SHS</i>	\$	680.00 <i>600</i>
3	1SET REAR BUMPER CLIPS <i>new</i>	\$	35.00 ✓
TOTAL		\$	995.00
 <u>LABOUR CHARGES :</u>			
1	TO KNOCK OUT DENT, CUT/WELD REAR PANEL, REAR SPARE TYRE PANEL AND REPLACE ACCIDENT PARTS	\$	1,200.00 <i>900</i>
2	TO SPRAY PAINTING ON ACCIDENT PORTION	\$	1,100.00 <i>1000</i>
3	TO CHECK WIRING	\$	30.00 ✓
4	TO REMOVE, REFIX CUSHION AND INNER TRIM	\$	120.00 <i>80</i>
5	TO REPLACE REVERSE SENSOR AND REAR SPOILER	\$	150.00 <i>50</i>
6	TO REMOVE, REPLACE REAR EXHAUST BOX	\$	120.00 <i>60</i>
7	TO REMOVE, REFIX FUEL TANK	\$ <i>in</i>	120.00 <i>X</i>
8	TO TUFF - KOTE	\$	90.00 <i>60</i>
TOTAL		\$	2,930.00
ESTIMATE PARTS AND LABOUR GRAND TOTAL :			\$ 9,439.77

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

P-4365.88
507
P-2182.94
SN-838
L-2180