

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHD7066Z
 Make : HYUNDAI
 Model : IONIQ
 DOA : 17.04.21

Date : 19.04.21
 Insurance: AIG
 MVA : JUMANI

Qty	Parts Description / Labour	Qty	Unit Price	Amount
1	FRT LH DOOR ASSY	1		\$1,797.20
2	REAR LH DOOR ASSY	1		\$1,789.90
3	FRT DOOR OUTER HANDLE	1		\$234.80
4	FRT DOOR OUTER HANDLE COVER	1		\$33.20
SUB TOTAL				\$3,855.10
LESS 20%				\$239.36
DISCOUNTED TOTAL			3084.08	\$3,615.74
	FRT DOOR COMFORTDELGRO LOGO	1		\$75.00
	REAR APPS LOGO	1		\$85.00
				\$160.00
Labour Charge				155
	PANEL BEATING			\$800.00
	SPRAYPAINT			\$600.00
	WIRING			\$50.00
	TRANSFER DOOR PARTS	2		\$240.00
TOTAL LABOUR			94209.08	\$1,690.00
ESTIMATE TOTAL			#2days	\$5,465.74

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation