

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pauline Tham

Date: 04 Jun 2021

**Preliminary Advice**

|                    |                                                                                                        |                         |              |
|--------------------|--------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : GBD5265A                                                                                             | Accident Date           | : 19/04/2021 |
| TP Vehicle No      | : SMX6726U                                                                                             | Assignment Date         | : 21/04/2021 |
| Make               | : TOYOTA NOAH HYBRID                                                                                   | Est. Duration of Repair | : 9          |
| Date of Inspection | : 20/04/2021                                                                                           |                         |              |
| Inspection At      | : SMARTONE AUTO PTE LTD (HQ)<br>8 KAKI BUKIT AVENUE 4, #08-09 PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |          |               |
|-----------------------------|----------|---------------|
| Repairer's Estimate (Gross) | :S\$     | 30,729.86     |
| Revised Amount              | :S\$     | 15,097.46     |
| Check Items (Estimated)     | :S\$     | 0.00          |
| Total                       | :S\$     | 15,097.46     |
| <br>Lump Sum Repair         | <br>:S\$ | <br>12,000.00 |

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :