

SKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
JOSHUA
POH ENG HENG
566 PASIR RIS STREET 51
#10-114
Singapore 510566

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

20-04-2021
5211043795
201009404M
30001
2021015085/ 1
19-04-2021
TIOW CHUAN CHEE

License plate SME4345Z	Model code 5E33BD	First registration 28-09-2018	VIN TMBBP7NE4J0329934	Model Octavia Ambition 1.0 I TSI 85kW DSG	Mileage 45,333
---------------------------	----------------------	----------------------------------	--------------------------	--	-------------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
5E0807221N	Cover For FRT BUMPER	1	pcs.	1,371.14	#1	1,371.14	1,467.12
5E0807724A	Support Pa BUMPER INNER BRACKET RH	1	pcs.	43.78	#1	43.78	46.84
5E0807184A	Guide Piec RHS BUMPER SIDE BRACKET	1	pcs.	34.59	#1	34.59	37.01
5E0919485G	Sensor bracket	1	pcs.	12.93	#1	12.93	13.84
5E0919486G	Sensor bracket	1	pcs.	12.93	#1	12.93	13.84
5E0919485F	Sensor bracket	1	pcs.	12.93	#1	12.93	13.84
5E0919486F	Sensor bracket	1	pcs.	12.93	#1	12.93	13.84
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	78.91	#1	78.91	84.43
D 822150A1	Bonding Agent For Plastic	1	pcs.	62.81	#1	62.81	67.21
5E2941016C	Halogen He H/LAMP RH	1	pcs.	959.00	#1	959.00	1,026.13
5E0807682F 9B9	Cover For RHS FOG LAMP LOWER GRILLE	1	pcs.	48.36	#1	48.36	51.75
5E0941700F	Halogen Fo FOG LAMP RH	1	pcs.	263.62	#1	263.62	282.07
5E0821106C	Fender RH	1	pcs.	616.26	#1	616.26	659.40
5E0821142A	Fender - B FENDER BRACKET RH	1	pcs.	98.92	#1	98.92	105.84
N 90959602	Rivitted Cap Nut	4	pcs.	2.23	#1	8.92	9.54
5E0809958D	Wheelhouse RHS FENDER LINER	1	pcs.	156.77	#1	156.77	167.74
	LABOUR	3	pcs.	840.00	#1	2,520.00	2,696.40
	SPRAY PAINT	4	pcs.	800.00	#1	3,200.00	3,424.00

AIG DIRECT SETTLEMENT
DOA: 19/04/2021
TP VEH: GBK8166X
SURVEY BY:

Quotation valid till 26-04-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	9,514.80	7%	719.24	10,274.80	10,994.04
Total	760.00	9,514.80		719.24	10,274.80	10,994.04

SKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation
Non-binding - Preview

Page	2/2
Document no.	
Document date	20-04-2021
Customer no.	5211043795
Customer GST-ID	201009404M
Dealer	30001
Job order number	2021015085/ 1
Job order date	19-04-2021
Service Advisor	TIOW CHUAN CHEE

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
JOSHUA
POH ENG HENG
566 PASIR RIS STREET 51
#10-114
Singapore 510566

License plate SME4345Z	Model code 5E33BD	First registration 28-09-2018	VIN TMBBP7NE4J0329934	Model Octavia Ambition 1.0 I TSI 85kW DSG	Mileage 45,333
---------------------------	----------------------	----------------------------------	--------------------------	--	-------------------

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

Rashid
Hp 90010068
4 days

23/04/21 @ 1145

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: