

原摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 08102600E

76 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Authorised
Survey After Point
6 days

REPAIR ESTIMATE FOR SJA3833U

No.	Qty	List Items	
1	1	Front bumper	\$ Bu 562.90 —
2	1	Front bumper LH side retainer	\$ Oil 50.70 —
3	1	LH headlamp	\$ Su 572.40 X
4	1	Front LH fender	\$ Bu 688.90 ✓
5	1	Front LH fender signal lamp	\$ Su 45.80 X
6	1	Front LH fender "VVTI" emblem	\$ nu 41.70 —
7	1	Front LH 1/4 glass moulding	\$ Su 179.20 X
8	1	Front LH fender under shield	\$ CM 275.20 —
9	1 set	Front fender under shield clips	\$ nu 40.00 —
10	1	Front LH shock absorber	\$ Bu 411.70 2
11	1	Front LH lower arm	\$ lu 577.95 X
12	1	Front LH knuckle arm	\$ Bu 402.31 2
13	1	Front LH wheel hub & bearing	\$ nu 202.90 2
14	1	Front LH door 1120.50	\$ R 1,221.90 X
15	1	Front LH door protector	\$ nu 202.90 —
16	1	Front LH door checker	\$ su 106.75 X
17	1	Front LH door hinge (Top & bottom)	\$ R 195.00 X
18	1	Front LH door inner trim board	\$ su 677.50 X
19	1 set	Front LH door inner trim board clips	\$ nu 60.00 X
20	1	LH rocker panel	\$ R 411.75 X
			\$ 6,927.46
			Less 25% \$ 1,731.87
			Total : \$ 5,195.60

Roll over

wheel
alignment

Special Nett Items

21	1	Front LH sports rims	\$ Rd 400.00 28000
22	1	Front LH tyre	\$ su 220.00 X
			Total : \$ 620.00

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$ 1,000.00 600
2	To putty and spray Spray Paintings charges.	\$ 1,000.00 750
3	To check wirings and lightings.	\$ 40.00 200
4	To remove, refit door fittings.	\$ nu 80.00 X
5	To remove, refit front LH under carriages.	\$ 220.00 140
6	To conduct computerise wheel alignment test.	\$ 80.00 60
7	To supply and apply anti-rust treatment	\$ 100.00 30
		Total : \$ 2,520.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Total Parts and Labour : \$ 8,335.60