

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find   Next
---	---	---	--------	---	---	---	---	------	---	---	-------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref: CS/EG121004954/f3		
5 TEMASEK BOULEVARD		Date: 20/04/2021		
#04-05 SUNTEC TOWER FIVE		Code: EGI		
SINGAPORE 038985				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
<b>Insured Veh.</b>	SMX 6822A	<b>Veh. Inspected</b>	SLM 2910A	
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00	
<b>Claim No.</b>	CDMPG21000693	<b>Excess (\$)</b>	0.00	
<b>Assign From</b>	PAULINE SOH	<b>Assign Date</b>	20/04/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
<b>Make &amp; Model</b>		<b>c.c</b>	0	
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>		
<b>Chassis No.</b>		<b>Colour</b>		
<b>Odometer</b>	-	<b>Steering</b>		
<b>Brakes</b>		<b>Modification</b>		
<b>General</b>				
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>				mm
<b>L/H Front Tyre</b>				mm
<b>R/H Rear Tyre</b>				mm
<b>L/H Rear Tyre</b>				mm
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
<b>Accident Date</b>	09/04/2021	<b>Inspection Date</b>	20/04/2021	
<b>Survey held at</b>	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				