

UPA HS14070NG

Not Authorized
Date

20/4/21

1/5 \$17,000 /
10 days.

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

VEHICLE No: GBJ 4909B

1PC	FRONT BUMPER	580.60	Dis	\$822.10	✓
1PC	FRONT BUMPER SIDE HOLDER O/S	68.45	Cre	\$105.90	✓
1PC	FRONT BUMPER REINFORCEMENT	435.91	Benf	\$611.20	✓
2PCS	FRONT BUMPER REINFORCEMENT STAYS @\$155.00		o/s Benf	\$310.00	WC
1PC	FRONT BUMPER TOP BEAM	188.60	Benf	\$289.60	✓
1PC	FRONT BUMPER TOW COVER		ms	\$20.80	✓
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	66.50	Bro	\$145.00	✓
1PC	FRONT BUMPER FOG LAMP O/S		MF	\$425.00	X
1PC	FRONT BUMPER CENTRE GRILLE	166.20	Dis	\$188.90	✓
1PC	FRONT GRILLE TOP	481.00	Benf	\$565.10	✓
1PC	FRONT GRILLE BOTTOM		Cre	\$688.10	✓
1PC	FRONT GRILLE INNER		NS	\$545.10	X
1PC	HEADLAMP O/S	704.35	Bro	\$1,455.10	✓
1PC	FRONT DOOR O/S	1568.80	Dis	\$1,845.20	✓
1PC	FRONT DOOR GLASS OUTER MOULDING O/S		17	\$105.20	X
1PC	FRONT DOOR GLASS CHANNEL O/S		17	\$181.65	X
1PC	FRONT DOOR GLASS REGULATOR O/S		17	\$366.20	X
1PC	FRONT DOOR GLASS REGULATOR MOTOR O/S		17	\$495.50	X
2PCS	FRONT DOOR HINGES @\$115.00		Twl	\$230.00	✓
1PC	FRONT DOOR OUTER PILLAR STRIP O/S	199.20	Twl	\$288.20	✓
1PC	FRONT DOOR CHECKER O/S		Twl	\$151.00	✓
1PC	FRONT DOOR OUTER HANDLE O/S		17	\$180.80	X
1PC	FRONT DOOR INNER LOCK O/S		JM	\$435.10	✓
1PC	FRONT DOOR INNER RUBBER O/S	288.20	rel	\$311.80	✓
1PC	FRONT DOOR INNER TRIM BOARD O/S		17	\$655.10	X
1SET	FRONT DOOR INNER TRIM BOARD CLIPS O/S		rel	\$50.00	✓
1PC	FRONT DOOR MIRROR ASSY O/S		17	\$1,050.00	X
1PC	FRONT DOOR OUTER PILLAR O/S		Body	\$1,022.80	✓
1PC	FRONT DOOR INNER PILLAR O/S	899.10	Body	\$988.10	✓
1PC	FRONT DOOR REAR PILLAR O/S	641.10	Body	\$655.10	✓
1PC	FRONT DOOR PILLAR LOWER MEMBER O/S		Twl	\$355.20	✓
1PC	FRONT STEP PANEL O/S	285.50	Dis	\$455.10	✓
1PC	FRONT STEP GARNISH O/S	299.20	Dis	\$422.10	✓
1PC	FRONT WHEEL ARCH PANEL O/S		Bro	\$545.50	✓
1PC	FRONT WHEEL ARCH PANEL TOP GARNISH O/S		Dis	\$188.90	✓
1PC	BONNET		R	\$1,450.00	X
1PC	BONNET LOGO	68.10	rel	\$85.10	✓
1PC	BONNET INNER LOCK		17	\$165.10	X
1PC	FRONT CORNER PANEL O/S		Bro	\$455.10	✓
1PC	AIR CLEANER BOX ASSY	680.50	Bro	\$820.20	✓
1PC	AIR CLEANER BOX FILTER		Dis	\$128.10	✓
1PC	FRONT WIRE HARNESS ASSY	566.10	Cre	\$655.20	✓
1PC	FRONT WIRE HARNESS BRACKET	188.20	Cre	\$205.20	✓

252

12802.31

1PC	FRONT BRAKE BOOSTER PUMP		DD	\$1,286.90	✓
1PC	FRONT BRAKE BOOSTER SWITCH		11	\$299.80	X
1PC	FRONT SUPPORT PANEL		Sent	\$611.20	✓
1PC	AIR CON CONDENSER		Pur	\$1,245.20	✓
1PC	AIR CON CONDENSER DISCHARGE PIPE		11	\$322.80	X
1PC	AIR CON SUCTION PIPE		11	\$562.20	X
1PC	AIR CON LIQUID PIPE		11	\$288.90	X
1PC	AIR CON BLOWER ASSY		11	\$1,655.10	X
1PC	AIR CON COOLING COIL		11	\$1,698.10	X
1PC	AIR CON HEATER ASSY		11	\$1,845.10	X
1PC	INTER COOLER	1562.10	Pur	\$1,866.10	✓
1PC	INTER COOLER INTAKE DUCT		Cre	\$148.60	✓
1PC	RADIATOR ASSY	2110.60	Pur	\$2,211.20	✓
1PC	RADIATOR TOP MOUNTING		11	\$28.80	X
1PC	RADIATOR FAN COWLING		11	\$313.10	X
1PC	RADIATOR FAN MOTOR		11	\$1,281.10	X
1PC	RADIATOR SUB TANK		11	\$186.95	X
1PC	FRONT CHASSIS MEMBER O/S		R	\$1,285.10	X
1PC	DASHBOARD		11	\$788.10	X
1PC	DASHBOARD REINFORCEMENT		11	\$1,288.10	X
1PC	FRONT FLOOR PANEL	1455.10	crumpled/Buc	\$1,855.10	✓
1PC	FRONT FLOOR PANEL TOP CARPET		SVL	\$688.00	X
1PC	FRONT WINDSCREEN		11	\$1,298.10	X
1PC	FRONT WINDSCREEN MOULDING		rec	\$112.20	✓
1PC	ACCELERATOR PEDAL		11	\$155.10	X
1PC	BRAKE PEDAL		11	\$156.20	X
1PC	FRONT SHOCK ABSORBER O/S		11	\$181.95	X
1PC	FRONT KNUCKLE ARM O/S	851.10	Daged	\$981.10	✓
1PC	FRONT WHEEL HUB BEARING O/S		Daged	\$255.10	✓
1PC	FRONT TOP ARM O/S	611.20	Sent	\$645.10	✓
1PC	FRONT LOWER ARM O/S		11	\$761.10	X
1PC	FRONT STEERING RACK ASSY		11	\$2,880.10	X
1PC	FRONT LINK ARM O/S		11	\$155.80	X
				\$50,451.85	

S.NETT

1PC	FRONT TYRE O/S		cut	\$180.00	60% 108
1SET	FRONT BUMPER CLIPS		rec	\$50.00	✓
1PC	FRONT WHEEL HUB CAP O/S		11	\$80.00	X
1PC	FRONT RIM O/S		su	\$150.00	X

TO CHECK WIRING	\$50.00	30
TO CONDUCT WHEEL ALIGNMENT	\$120.00	80
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	\$280.00	120
TO DISMANTLE & REFIX FRONT WINDSCREEN	\$150.00	100
TO DISMANTLE & REPLACED BRAKE BOOSTER PUMP	\$150.00	60
TO TRANSFER FRONT DOOR MECHANISM	\$100.00	60

TO DISMANTLE & REFIX FRONT DASHBOARD	\$380.00	200
TO SPRAY RUST PROOFING	\$180.00	100
TO REFILL AIR CON GAS	\$120.00	100
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$3,800.00	1800
TO PUTTY & SPRAY PAINTING	\$2,580.00	1300
TOTAL	\$73,776.15	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-23051-61
 257
 17288.70
 4108