

CKW / 805465703

ORTDELGRO ENGINEERING PTE LTD
AIR ESTIMATE

Vehicle No.: SH9513K
 Make : TOYOTA
 Model : PRIUS
 DOA : 15.04.2021

Date : 15.04.2021
 Insurance: NTUC
 MVA : CHIANG
 Admin :

| Part No. | Parts Description / Labour | Qty | Unit Price | Amount |
|----------|--|--------|------------|-------------------|
| 1 | REAR TRUNK LID LOGO (PRIUS) | | | \$60.80 |
| 1 | REAR TRUNK LID LOGO (HYBRID) | | | \$52.40 |
| 1 | REAR TRUNK LID LOGO (TOYOTA STAR) | | | \$52.90 |
| 1 | REAR BUMPER | | | \$458.60 |
| 1 | REAR BUMPER CENTRE MOULDING | | | \$552.60 |
| 1 | REAR BUMPER TOWING COVER | | | \$82.70 |
| 10 | REAR BUMPER CLIPS | | | \$22.00 |
| 1 | REAR BUMPER REINFORCEMENT | | | \$318.80 |
| | SUB TOTAL | | 574.60 | \$1,600.80 |
| | LESS 25% | | 430.95 | \$400.20 |
| | DISCOUNTED TOTAL | | | \$1,200.60 |
| | REAR TRUNK LID APPS STICKER | | | \$40.00 |
| | REAR TRUNK LID COMFORT & TEL NO. STICKER | | | \$60.00 |
| | REAR BUMPER REVERSE SENSOR | | | \$135.70 |
| | | 10.00% | | \$212.13 |
| | Labour Charge | | | |
| | Panel Beating | | | 350 \$600.00 |
| | Spray Painting Charge | | | 250 \$300.00 |
| | Wiring Charge | | | 111 \$60.00 |
| | Tuff Kote | | | 111 \$90.00 |
| | Remove/Refix Reverse Sensor | | | 30 \$60.00 |
| | TOTAL LABOUR | | 630 | \$1,110.00 |
| | ESTIMATE TOTAL | | 1060.95 | \$2,522.73 |
| | | | 2 days # | |

x2
 x } us
 x }
 Ry
 de -
 x ny
 mel
 x un

x \$40.00 Nett
 x \$60.00 Nett
 L? \$135.70 Nett

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749
 'WP' 15/4/21 @ 4pm
 02 days
 P/P Resurvey after repair.
 Tanpin @ lkhaut.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: