

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 5019
Date Estimated : 19/04/2021
Prepared By : Lim Luo Shan Vion

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Sim Chong Teck (Shen Zongde)
11 Lim Tua Tow Road
#05-23 Casa Cambio

Singapore 547803

- ACCOUNT - 31432

China Taiping Insurance (Singapore) Pte Ltd
3 ANSON ROAD
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN7575X	VF3MRHNSUKL145076	12/01/2021	5008 1.2 Allure	4287

DESCRIPTION

TO CONDUCT TP CLAIMS - CHINA TAIPING - SMY9582Y - D.O.A.
16.04.21

VALUE
0.00

TO REPAIR FRONT BUMPER, FRONT FENDER RH, BONNET & ALL
AREAS AFFECTED BY THE ACCIDENT.

600 1,800.00

TO RESPRAY FRONT BUMPER, FRONT FENDER RH Bonnet.

1800 2,400.00

TO TRANSFER FRONT PREDESTRIAN SENSOR

NN X 300.00

TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING

120 250.00

TO CHECK STEERING GEOMETRY AND CONDUCT FULL
ALIGNMENT

300 600.00

TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING

150 280.00

TO REPROGRAMME ECU AND CLEAR FAULT CODE AFTER THE
ACCIDENT REPAIR WORKS

✓ 600.00

SUNDRIES

20 100.00

Total Labour 1: 6,330.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1617977580	FOGLAMP FINISHER SET	1	90.00	10.00	81.00
98252888XT	FRONT WING MOULDING RH	1	210.00	10.00	189.00
9838610980	WEATHERSTRIP HEADLAMP	1	17.00	10.00	15.30
1674017880	BARE HEADLAMP RH	1	2,400.00	10.00	2,160.00
98096873ZR	ALLOY WHEEL 18 DETROIT BRILLANT	1	700.00	10.00	630.00

Total Parts : 3,075.30

ANCE

ge Automotive Limited)

tion No. 62907220C GST Registration No. M2-0000551-1

ad
re
288
1373



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 5019
Date Estimated : 19/04/2021
Prepared By : Lim Luo Shan Vion

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN7575X	VF3MRHNSUKL145076	12/01/2021	5008 1.2 Allure	4287

4 Days.

After repair photos.

Guo Qiang - 82880282

Guo Qiang @ lkk auto. com

03/5/21.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To survey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer Name & Signature / Company Stamp	Date	Labour 1	:	6,330.00
		Parts	:	3,075.30
		Labour 2	:	0.00
		Excess	:	0.00
		Total GST @ 7%	:	658.37
		Grand Total	:	10,063.67

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.