



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no. : 6631 1188



TOYOTA

Steve (LKK) WML RL
83728813 3 djs
26/4/21, 19 Nov PIP, B, BL SJ

ESTIMATE

Account Details			Account No.		Customer Details		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Kee Kian Pheng		
			Document No. 0		21A Lorong G Telok Kurau		
			Document Date 17/04/2021		Singapore 426322 Mobile: 93236286		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2015	ZRE171R	GEXGKZ S2	04/05/2015	SDA8628J	0	20891	67/TP/SDA8628J
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR053REH104531443		1ZRX503797	60	Sam San Joi	-/-/- 0.00 -/-/-		0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP CLAIM TP-SLL3216U ACC DATE:14/04/2021 DRIVE IN:16/04/2021 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30.00 ✓	
2	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				180.00 ✓	
3	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				180.00 ✓	
4	Z	BP-SLANT SUPPLY SEALANT (NETT)-REAR END PANEL				60.00 X	
5	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET GARNISH AND TRIMMING TO ASSIST REPAIR				360.00 ✓	
6	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00 ✓	
7	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS 719				3600.00	
8	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR 590 EAS				2950.00	
9	1	S52159-0Z904 COVER,RR BUMPER ✓	1.00	556.40		556.40	
10	2	S52563-02250 RETAINER,RR BUMPER L ✓	1.00	60.40		60.40	
11	3	S52576-02140 RETAINER,RR BUMPER L ✓	1.00	109.30		109.30	
12	4	S52562-02250 RETAINER,RR BUMPER R ✓	1.00	60.40		60.40	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9

17 UBI ROAD 4
SINGAPORE 408611, Tel no. : 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Kee Kian Pheng
	Document No. 0	21A Lorong G Telok Kurau Singapore 426322
	Document Date 17/04/2021	Mobile: 93236286

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2015	ZRE171R	GEXGKZ S2	04/05/2015	SDA8628J	0	20891	67/TP/SDA8628J

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR053REH104531443	1ZRX503797	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	5	S52575-02140 RETAINER,RR BUMPER R	1.00	109.30		109.30
14	6	S52161-0K040 CLIPS	10.00	4.10		41.00
15	7	S52023-02190 REINFORCEMENT,RR	1.00	399.50		399.50
16	8	S52182-02160 ARM, RR BUMPER, OUTE	1.00	68.20		68.20
17	9	S52181-02190 ARM, RR BUMPER, OUTE	1.00	68.20		68.20
18	0	S58307-02380 PANEL,LAMP LOWER	1.00	670.00		670.00
19	1	S58387-02240 PLATE,RR FLOOR	1.00	241.90		241.90
20	2	S64771-02390 CO COVER, SPARE WHEEL	1.00	267.00		267.00
21	3	S64401-02B71 PANEL SUB-ASSY, LUGG	1.00	793.20		793.20
22	4	S64461-02220 WEATHERSTRIP, LUGGAG	1.00	175.80		175.80
23	5	S64600-02080 LOCK ASSY, LUGGAGE C	1.00	399.50		399.50
24	6	S64621-06080 STRIKER, LUGGAGE COM	1.00	15.30		15.30
25	7	S75431-02090 LUGGAGE COMP EMBLEM,	1.00	61.60		61.60
26	8	S75442-02330 EMBLEM,SYMBOL	1.00	41.00		41.00
27	9	S75442-02340 EMBLEM,SYMBOL	1.00	45.60		45.60
28	0	S81560-02780 LAMP ASSY,RR COMB LH	1.00	379.80		379.80
29	1	S81550-02780 LAMP ASSY,RR COMB RH	1.00	379.80		379.80
30	2	T89997-30070 ELECTRICAL ANTENNA,	1.00	192.20		192.20
31	3	SPZ061-12021 17 BACK SENSOR 1D4 310A	1.00	159.75		159.75

For & on behalf of Auto Consultants hence notify Borneo Motors (Singapore) Pte Ltd.	Customer's Signature	Charge Summary	Total
- To survey before repair spray painting - To display damaged part(s) during recovery - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company	Receipt of vehicle	Parts 5,295.15 Labour 7,540.00 Sublet 0.00 Lubrication/Fluid 0.00 Others 0.00	12,835.15 GST 7.00% 898.46 Less 0.00 Amount Due 13,733.61

Acknowledged by Repairer

Signature:

Date:

Customer Copy