

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21005026/ARS3Q2
Date: 20/09/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SGW4100P

Date of Loss: 18/04/2021

Policy No:

Insured Vehicle No :

SMV9894H

Nature of Claim:

TP

Claim No:

9448649103SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGW4100P**

Make & Model: TOYOTA CAMRY, 2.4 ABS AIRBAG (A)

Reg. Date: 26/11/2009 (Man. Year: 2009)

Colour: Grey

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 2AZE156726

Chassis No: MR053BK4007037601

Odometer: 86932 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Front Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Tyre Size:

215/60 R16

Rear Left Side:

Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,809.15	3,739.70	2,069.45	35.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	1,890.00	620.00	24.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,319.15	5,629.70	2,689.45	32.33
Approved Total (Overridden) (S\$)		4,500.00		

(S\$)	8,319.15	4,500.00	3,819.15	45.91
+ GST 7.00/7.00% (S\$)	582.34	315.00	267.34	45.91
Nett Amount (S\$)	8,901.49	4,815.00	4,086.49	45.91
+ Car Rental (9.0 x S\$120.00/day) (S\$)		1,080.00		
Nett Liability (S\$)		5,895.00		

INSPECTION

Date of Assignment: 20/04/2021

Date Inspected: 20/04/2021

Estimated Period of Repair: 7.0 days

Inspected At:

J-mart Motor Pte Ltd (HQ)
Blk 5 Defu Lane 10, #01-578
Singapore 539186**Adjuster:** Jaslin Kok Chin Yi**Manager:** ADRIAN LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	895.00 FL	*895.00 FL
2	1		*LOGO EMBLEM	Necessary	75.00 FL	*75.00 FL
3	1		*2.4 EMBLEM	Necessary	45.00 FL	*45.00 FL
4	1		*CAMRY EMBLEM	Necessary	58.00 FL	*58.00 FL
5	1		*BOOTLID LOCK	Damaged	380.00 FL	*380.00 FL
6	1		*BOOTLID W/STRIP	Not Necessary	225.00 FL	*- FL
7	1		*BOOTLID REFLECTOR	N/S Cut	790.00 FL	*395.00 FL
8	1		*TAILLAMP	N/S Cut	1,140.00 FL	*570.00 FL
9	1		*REAR BUMPER	Distorted	665.00 FL	*665.00 FL
10	2		*REAR BUMPER RETAINER LONG	Necessary	120.00 FL	*120.00 FL
11	2		*REAR BUMPER RETAINER SHORT	Not Necessary	104.00 FL	*- FL
12	1		*REAR BUMPER REFLECTOR	N/S Cut	115.20 FL	*57.60 FL
13	6		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Dented	395.00 FL	*395.00 FL
15	1		*END PANEL	Distorted	695.00 FL	*695.00 FL
16	1		*END PANEL INNER GARNISH	Deformed	400.00 FL	*339.00 FL
17	1		*SPARE TYRE CARDBOARD	Not Necessary	400.00 FL	*- FL
18	1		*SPARE TYRE PANEL	Repair	880.00 FL	*- FL
19	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,662.20	4,919.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,853.05	1,179.90
Total Parts (\$\$)	5,809.15	3,739.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	1,000.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	30.00	30.00
4	RUST PROOFING	New	80.00	60.00
Gross Labour Cost (S\$)			2,510.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >