

(00/11/14)

Surveyor

T Lim

REF:

CS/CT121005046/Bgf:3

Shian Chan

ASSIGNMENT

From: Date: 22/4/2021

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SM 467 T

at Workshop m/s Bifrost Auto

of 8 Kaki Bt Aved Premier #01-49

Insured:

Policy No.

Claims No. SNM21D202312/C02

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 80,000/2

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SM 467 T

Yr Regn: 17/6/2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Harrier 2.0 c.c 1986

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

107164

T/Radio: Insured / Std / NI / NA

Eng/No:

3ZRB75125

C/No:

ZSU600074613

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55/18

R: 235/55/18

S/DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

21/4/2021

D.O.I.

22/4/2021

Survey held at

Bifrost Auto

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

25/5/2021 @ 12.04pm Range 14,000/2 - 15,000/2
Revise to Jacqueline via Merimen.

Recommended COR is LS \$14,200/2

21/05/21 @ 12.05pm Mr Lim Finalised with Suanne
at LS \$14200, 8 days. (Red \$16876.42, 54%)

MV 80,000/2

PV 46,073/2

NV 33,927/2

Date/Time, File Pass to?



Preli. Report

1) 25/05 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format: MER-TP

Lump Sum A.D.I. (\$) 14200

Survey
23/4/2021

1330hrs

Tan
Lim

Resurvey

27/4/2021

1420hrs

Tan
Lim

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Company Reg No: 201929175W

Vehicle No:

Model and make:

Chassis No:

SMQ467T

Toyota Harrier

ZSU600074613

Qty Spare Parts

List Price (\$)

| | | | |
|---|---|----|-----------------------|
| 1 | Front bumper | \$ | ✓ 1,450.50 BR ✓ |
| 1 | Front bumper upper arm | \$ | 301.10 NSX |
| 1 | Front bumper reinforcement | \$ | 460.70 NDX |
| 1 | Front bumper reinforcement sponge | \$ | ✓ 89.80 BR ✓ |
| 1 | Front bumper RH towing cover | \$ | 34.90 50.60 } DL ✓ |
| 1 | Front bumper LH towing cover | \$ | 34.90 50.60 } |
| 1 | Front bumper RH side retainer | \$ | ✓ 115.21 } NECV |
| 1 | Front bumper LH side retainer | \$ | ✓ 115.21 } |
| 1 | Front bumper centre lower grille | \$ | ✓ 273.70 BR ✓ |
| 1 | Front bumper RH fog lamp cover | \$ | 83.94 NDX |
| 1 | Front bumper lower spoiler | \$ | 286.80 NSX |
| 1 | Front bumper RH air guide | \$ | 17.20 NSX |
| 1 | Front grille with emblem | \$ | ✓ 511.60 NECV |
| 1 | Front centre support panel | \$ | 460.80 675.40 DD ✓ |
| 1 | RH headlamp assy | \$ | ✓ 3,370.53 BR ✓ |
| 1 | RH headlamp lower beam | \$ | 91.50 NDX |
| 1 | RH headlamp lower beam sponge | \$ | ✓ 21.80 BR ✓ |
| 1 | RH headlamp panel | \$ | ✓ 216.70 DD ✓ |
| 1 | LH headlamp assy | \$ | ✓ 3,370.53 BR ✓ |
| 1 | LH headlamp lower beam | \$ | ✓ 91.50 BR ✓ |
| 1 | LH headlamp lower beam sponge | \$ | ✓ 21.80 BR ✓ |
| 1 | LH headlamp panel | \$ | |
| 1 | Aircon condenser | \$ | 1,460.80 NDX |
| 1 | Front RH fender | \$ | 1,022.10 NDX |
| 1 | Tailgate | \$ | 1712.05 2,379.00 DD ✓ |
| 1 | Tailgate emblem | \$ | ✓ 76.00 NECV |
| 1 | Tailgate reverse camera | \$ | 940.30 NDX |
| 1 | Tailgate RH side rubber sensor | \$ | 732.00 NSX |
| 1 | Tailgate LH side rubber sensor | \$ | 732.00 } |
| 1 | Tailgate windscreen glass rubber moulding | \$ | ✓ 151.00 NECV |
| 1 | Tailgate outer garnish | \$ | 1132.50 1,302.00 BR ✓ |
| 1 | Tailgate outer garnish centre emblem | \$ | ✓ 62.00 NECV |
| 1 | Tailgate RH lamp assy | \$ | ✓ 498.60 BR ✓ |
| 1 | Tailgate LH lamp assy | \$ | 498.60 NDX |
| 1 | Tailgate mechanism lock with cover | \$ | 559.70 974.00 BR ✓ |
| 1 | Tailgate weatherstrip | \$ | 357.00 442.00 TN ✓ |

21/05/21@12:05pm Mr Lim Finalised with Suanne
at LS \$14200. 8 days. (Red)

- 1 Tailgate inner trim board
- 1 RH taillamp assy
- 1 RH taillamp lower bracket
- 1 LH taillamp assy
- 1 LH taillamp lower bracket
- 1 Rear fender RH inner trim board
- 1 Rear fender LH inner trim board
- 1 Rear bumper
- 1 Rear bumper RH side retainer
- 1 Rear bumper LH side retainer
- 1 Rear bumper RH reflector
- 1 Rear bumper LH reflector
- 1 Rear bumper lower spoiler
- 1 Rear bumper inner sponge
- 1 End panel
- 1 End panel inner garnish
- 1 End panel antenna sensor
- 1 Rear compartment panel
- 1 Rear compartment panel top inner board
- 1 Rear compartment panel RH side tool tray
- 1 Rear compartment panel LH side tool tray
- 1 Rear compartment panel RH inner top tray
- 1 Rear compartment panel top sponge
- 1 Rear compartment panel top board
- 1 Rear spare tyre retainer lock

| | | | |
|----|---------|----------|---------|
| \$ | ✓ | 578.30 | BR ✓ |
| \$ | ✓ | 505.00 | BR ✓ |
| \$ | 75.00 | 86.00 | BR ✓ |
| \$ | ✓ | 505.00 | BR ✓ |
| \$ | 75.00 | 86.00 | BR ✓ |
| \$ | | 545.00 | } NDX |
| \$ | | 545.00 | |
| \$ | 1395.30 | 1,415.00 | BR ✓ |
| \$ | 79.30 | 86.40 | } NEC ✓ |
| \$ | 79.30 | 86.40 | |
| \$ | ✓ | 62.50 | } BR ✓ |
| \$ | ✓ | 62.50 | |
| \$ | | 486.00 | NDX |
| \$ | ✓ | 145.00 | BR ✓ |
| \$ | ✓ | 796.00 | DD ✓ |
| \$ | 360.89 | 446.10 | BR ✓ |
| \$ | ✓ | 165.00 | BR ✓ |
| \$ | | 825.00 | NDX |
| \$ | | 885.00 | NDX |
| \$ | | 175.00 | } NDX |
| \$ | | 175.00 | |
| \$ | | 465.00 | |
| \$ | | 339.00 | |
| \$ | | 667.00 | NDX |
| \$ | | 45.60 | NDX |

\$ 19,611.63 33,115.22
 -25% \$ 4,902.91 8,278.81
 \$ 14,708.72 24,836.42

Qty Spare Parts

- 1set Front bumper clips
- 1 Front number plate
- 1set Front grille clips
- 1 Radiator coolant
- 1 Tailgate windscreen glass sealant
- 1 Tailgate windscreen glass inner seal
- 1set Tailgate inner trim board clips
- 1set Rear bumper clips
- 1set Rear bumper reverse sensor
- 1 Rear number plate

| Special Nett (\$) | | | |
|-------------------|-------|--------|---------|
| \$ | 30.00 | 70.00 | } NEC ✓ |
| \$ | 50.00 | 70.00 | |
| \$ | 20.00 | 40.00 | |
| \$ | | 40.00 | NNX |
| \$ | 40.00 | 70.00 | } NEC ✓ |
| \$ | 20.00 | 50.00 | |
| \$ | 30.00 | 60.00 | |
| \$ | 30.00 | 70.00 | |
| \$ | | 280.00 | SC ✓ |
| \$ | | 70.00 | NDX |
| <hr/> | | | |
| 500.00 | | | |

Labour and painting

| | | |
|--|-----------|------------|
| Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels (front portion) | \$ 600.00 | 900.00 ✓ |
| Spray painting on affected panels (front portion and pearl white) | \$ 600.00 | 1,000.00 ✓ |
| Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels (rear portion) | \$ 600.00 | 1,000.00 ✓ |
| Spray painting on affected panels (rear portion and pearl white) | \$ 400.00 | 1,200.00 |
| Check wiring and lighting system (front and rear) | \$ 30.00 | 100.00 ✓ |
| Remove and reinstall radiator, hoses and fan assy to assist repairs. To refill radiator coolant | \$ | 180.00 NSX |
| Remove, reinstall and replace aircon condenser, pipes and fan assy to assist repairs. To refill aircon gas | \$ | 180.00 NSX |
| Apply rust coating on affected areas | \$ 50.00 | 100.00 ✓ |
| Remove and reinstall tailgate windscreen glass to assist repairs | \$ 120.00 | 200.00 ✓ |
| Transfer and replace tailgate inner mechanism to new tailgate | \$ 80.00 | 120.00 ✓ |
| Remove and replace rear inner trims, garnish and boards to assist repairs | \$ | 240.00 NNX |
| Remove and replace rear bumper reverse sensors | \$ 60.00 | 70.00 ✓ |
| Remove and replace tailgate reverse camera | \$ | 80.00 NNX |
| Towing fee | \$ | 50.00 NNX |

2540.00

Total:

\$ 31,076.42

17,748.72

3,549.74

14,198.98

@20%

4/8 14,200/2

TG Lim
21/5/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 26/04/2021 11:35 (SGT)
Date of Accident 21/04/2021 13:40 (SGT)
Exact Location of Accident Singapore
Additional Location Information WOODLANDS AVENUE 12
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMQ467T

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner SUGUMAR S/O KRISHNAN @ SAJID ABDULLAH
NRIC No SXXXX799D
Email Address SUGUSAJID@YAHOO.COM
Mobile Phone No (Phone) +65-96565454
Alternative Phone No +65-96565454

VEHICLE PARTICULARS

Manufacturer Toyota
Model TOYOTA / HARRIER ELEGANCE 2.0 A
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 2000

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5120299126
Cover Note Number -

DRIVER

Name of Driver SUGUMAR S/O KRISHNAN @ SAJID ABDULLAH
NRIC No SXXXX799D

| | |
|--|----------------------------------|
| Date Of Birth | 21/07/1950 |
| Occupation | Indoor |
| Date Of Driving Pass | 09/02/2006 |
| Driving experience | 15 YEARS AND 2 MONTHS |
| Gender | Male |
| Mobile Number | (Phone) +65-96565454 |
| Alt. Phone Number | +65-96565454 |
| Email Address | SUGUSAJID@YAHOO.COM |
| Address | BLK 181 #02-244 EDGEFIELD PLAINS |
| Address complement | - |
| Postcode | 820181 |
| Is the driver the policyholder? | Yes |
| If No, Relationship of the Driver with the Insured | - |
| Does Driver Own Other Vehicles? | No |
| Vehicle Registration Number of Other Vehicle Owned by Driver | - |
| Insurance Company of Other Vehicle Owned by Driver | - |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------|-----------------|
| Type of Accident | Chain Collision |
| Weather Conditions | Clear |
| Road Surface | Dry |

OTHER INFORMATION

| | |
|---|-----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 3 |
| Was anybody injured in the Accident? | Yes |
| Was any injured conveyed to hospital by ambulance? | No |
| Was any other material or property damaged? | Yes |
| Number of Passengers (Including Driver) | 2 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |

PASSENGER 1

| | |
|--------|---------------------------------|
| Name | HABIBULKEKHAIN BIN MOHD HUSSEIN |
| Gender | Male |

DETAILS OF POLICE ACTION

| | |
|---|----|
| Was the accident reported to the police? | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | - |

CIRCUMSTANCES OF ACCIDENT

21/05/21@12.05pm Mr Lim Finalised with Suanne
at LS \$14200, 8 days. (Red \$16876.42, 54%)

ATTACHMENT(S)

| | |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera? | No |
| Was there any audio recorded? | No |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|--------------------------|
| Vehicle Registration Number | GBK3854B |
| Vehicle Manufacturer | Toyota |
| Vehicle Model | TOYOTA / DYNA 3.0 MANUAL |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Commercial vehicle |

Name of Driver
 Contact Number
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBH6421M
 Vehicle Manufacturer Toyota
 Vehicle Model TOYOTA / DYNA 150 5MT
 Vehicle Variant
 Vehicle Colour
 Vehicle Category Commercial vehicle
 Name of Driver
 Contact Number
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number GBH6421M
 Vehicle Manufacturer Toyota
 Vehicle Model TOYOTA / DYNA 150 5MT
 Vehicle Variant
 Vehicle Colour
 Vehicle Category Commercial vehicle
 Name of Driver
 Contact Number
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1

Name of injured person SUGUMAR S/O KRISHNAN @ SAJID ABDULLAH
 Address
 Address Complement
 Post Code
 Approximate Age Years Old
 Injuries Sustained
 Injured person in which vehicle? SMQ467T
 Were seat belts worn? Yes
 Was this injured conveyed to hospital by ambulance? No

INJURED 2

Name of injured person HABIBULKEKHAIN BIN MOHD HUSSEIN
 Address
 Address Complement
 Post Code

SMQ467T
Yes
No

SKETCH PLAN

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/ can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be shed outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time
Sketch Plan


Driver's Signature (If driver is not the policyholder) / Date & Time

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vac@vacom.com.sg

Witnessed by Reporting Centre
Personnel
26 APR 2021

21/05/21@12.05pm Mr Lim Finalised with Suanne
at LS \$14200, 8 days. (Red \$16876.42, 54%)



A: SM 2467T
B: 66K 3354B
C: GBH 1421M

SLOW DOWN AND TOP. SUDDENLY, I FELT A HUGE IMPACT FROM THE REAR. THE IMPACT WAS SO GREAT THAT

CHAIN COLLISION

We declare the foregoing particulars are true in every respect.

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

26 APR 2021

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|---------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 799D |
| Vehicle Details | |
| Vehicle No.: | SMQ467T |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 21 May 2021 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | HARRIER ELEGANCE 2.0 A |
| Primary Colour: | White |
| Secondary Colour: | Black |
| Manufacturing Year: | 2016 |
| Engine No.: | 3ZR8751125 |
| Chassis No.: | ZSU600074613 |
| Maximum Power Output: | 111.0 kW (148 bhp) |
| Open Market Value: | \$29,424.00 |
| Original Registration Date: | 17 Jun 2016 |
| First Registration Date: | 17 Jun 2016 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$28,194.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 16 Jun 2026 |
| PARF Rebate Amount: | \$21,145.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 16 Jun 2026 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$49,156.00 |
| COE Rebate Amount: | \$24,928.00 |
| Total Rebate Amount: | \$46,073.00 |

The information contained herein is correct as at 21 May 2021

OK

MV 80,000/2
 PV 46,873/2
 NV 33,927/2

TGm Min
 21/5/2021



2 Owner Only, Low Interest Rate, Lowering Spring, Lane Departure Alert, Cruise Control, Audio Alpine X009 Design For Harrier, Carbon Fibre Steering, SilkBlaze Side Mirror Anti Glare Signal Led, SilkBlaze Full Body Kit&2 Pcs Rear Top Spoiler, Front Top Strut Bar &...

Posted: 12-May-2021 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier



Toyota Harrier 2.0A Premium Panoramic

N.A

27-Jul-2016

1,986 cc

SUV

SOLD

1 Owner Only High Specs Harrier Premium Advance Edition! Meticulously Well Maintained By Previous Owner With No Expense Spared In Pristine Immaculate Condition Assured! Guaranteed One Of The Best Condition Unit In The Resale Market! 100% Accident Free...

Creative Auto

Posted: 20-Apr-2021 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier



Toyota Harrier 2.0A Premium Panoramic

\$87,888

\$13,700 /yr

22-Jul-2016

1,986 cc

72,031 km

SUV

Available

1 Owner Only, Low Bank Interest Of 1.88%. Full Loan Scheme Available At 3.88% Only! Fresh New Paintwork Of Sparkling Pearl White Colour. Cheapest Premium Panoramic Roof Unit With Low Mileage! Inclusive Of Road Tax Till 07/21! Lane Departure Alert, Cr...

Posted: 28-Apr-2021 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier



Toyota Harrier 2.0A Elegance

\$82,800

\$13,420 /yr

18-Jul-2016

1,986 cc

76,244 km

SUV

Available

1 Owner, Sold Due To Under-Used, Accident Free And Original Paintwork, Well Preserved Condition, Newly Polished! Offering High Trade-In Quotes! Interest Rate From 1.88% From Reputable Bank! Whatsapp/Call Our Friendly Sales Consultant For Viewing/Appoin...

Car (S) Pte Ltd

Posted: 14-May-2021 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier



Protect your Car with sgCarMart Warranty

Drive your car worry-free with \$0 future car repair bills. sgCarMart Used Car Warranty covers the most expensive-to-repair parts.

Find out more!



Toyota Harrier 2.0A Premium Panoramic

-

N.A

18-Jul-2016

1,986 cc

SUV

SOLD

Elegant Silver SUV, 'Premium' Model With Panoramic Moonroof And Electric Tailgate, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.

Prime Motor & Leasing

Posted: 14-Mar-2021 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier



Toyota Harrier 2.0A Elegance

\$82,800

\$13,450 /yr

13-Jul-2016

1,986 cc

45,449 km

SUV

Available

1 Owner Unit Only, Driven By Single Lady Owner! Transfer Count Due To Household Transfer, Lowest Interest Of 1.68% By Reputable Banks, High Loan Welcome! Extremely Genuine Low Mileage Of 45,449km Only! Beautifully Bidded Plate Number To Go...

Car (S) Pte Ltd

Posted: 18-May-2021 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier



Toyota Harrier 2.0A Elegance Panoramic

-

N.A

11-Jul-2016

1,986 cc

SUV

SOLD

The All Time Favourite Toyota SUV, Flawless Immaculate Underutilized Panoramic Unit, Best Ownership And Condition In Town, High COE Value Of \$56,000 Equivalent To High Paper Value, Fully Done Up To Showroom Unit Standard, New Paintwork, New Tyres, Ro...

Posted: 01-Mar-2021 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier



Toyota Harrier 2.0A Premium Panoramic

-

N.A

08-Jul-2016

1,986 cc

SUV

SOLD

Very Well Maintained, Accident Free, Trade In And Loan Available, Please Call For An Appointment.

Posted: 04-Apr-2021 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier



Toyota Harrier 2.0A Premium Panoramic

-

N.A

30-Jun-2016


1,986 cc

SUV

SOLD

Only One Owner, View To Appreciate, High Grade Model, Upgrade To 20 Inch Rims, No Repairs Needed, High Trade In And Loan Available.

Posted: 19-Apr-2021 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier



Toyota Harrier 2.0A Premium Panoramic

-

N.A

30-Jun-2016

1,986 cc

SUV

SOLD

Flawless Immaculate Underutilized Condition Driven Previously By Lady Banker Owner, The All Time Favourite Toyota SUV, High Specs Premium Model, Best Ownership And Condition In Town, High COE Value Of \$57,390 Equivalent To High Paper Value, Fully Done U...

Posted: 11-Mar-2021 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier

Toyota Harrier 2.0A Premium Panoramic

-

N.A

29-Jun-2016

1,986 cc

SUV

SOLD

1 Owner, Selling Fast, Low Mileage, Beautiful White Luxury SUV, Well Maintained And In Good Condition, Original Paintwork, New SMZ