

MBM WHEELPOWER PTE LTD



Your Ref: GBE2962K

Our Ref: ES2330A

To: AIG

CC

Fax

*Not Authored
Recovery B4 pain
4 days*

Date: 21/4/2021
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: B.M.W 216D
Chassis No.: WBA2E320005B44921
Engine No.: 30219523B37C15A
Year of Make: 2016
Accident Date: 17 April 2021

ESTIMATE FOR VEHICLE NO. : ES2330A

DESCRIPTION	QTY	List Price
FRONT BUMPER	1	\$ 1,700.00 ✓
FRONT BUMPER RH RETAINER	1	\$ 55.00 X
FRONT RH FOG LAMP BRACKET	1	\$ 175.00 ?
FRONT RH FOG LAMP CHROME	1	\$ 157.00 ✓
FRONT RH FOG LAMP COVER	1	\$ 143.00 ✓
FRONT RH FOG LAMP	1	\$ 325.00 ?
PARKING SENSOR - BLACK	2	\$ 640.00 ?
DECOULPING RING	4	\$ 60.00 ?
HEAD LAMP RH	1	\$ 3,060.00 ✓
Total:		\$ 6,315.00
LESS 10%		\$ (631.50)
Parts Total:		\$ 5,683.50

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.

TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)

TO REMOVE & REPLACE BUMPER SENSORS

TO CHECK & RECONNECT ALL NECESSARY WIRING

TO SPRAY PAINT ON THE AFFECTED AREAS

3501
800.00
300.00 ?
60.00 ✓
201
80.00
4401
800.00

Total: \$ 7,723.50
7% GST: \$ 540.65
Grand Total: \$ 8,264.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mbm wheelpower pte ltd
160 SIN MING DRIVE
#06-02
SIN MING AUTOCITY
t 62628888 f 64525333

Company Registration Number : 200204110W