



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI21000075/Gtf3e2-1 Date: 14/05/2021 Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMA 7978Z	Veh. Inspected	SKR 2592U	
Policy No.	DMPCSNW00055282001	Coverage (\$)	0.00	
Claim No.	SNM20D205085/C02/LEWLC	Excess (\$)	0.00	
Assign From	JENNY LEW	Assign Date	22/04/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MINI COOPER S COUNTRY MAN	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WMWZC32060WR77344	Colour	BROWN	
Odometer	130664 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R18	HABILEAD	6 mm	
L/H Front Tyre	225/45 R18	HABILEAD	6 mm	
R/H Rear Tyre	225/45 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	225/45 R18	CONTINENTAL	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	23/12/2020	Inspection Date	07/01/2021	
Survey held at	55 SERANGOON NORTH AVENUE 4, #02-10			
Repairer	1 STOP GARAGE PTE. LTD.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	