



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHEN XINYOU			Ref: CC4/ASM21005060/Kga3q2 Date: 09/06/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJQ 9560H	Veh. Inspected	SJK 8603G
	Policy No.	GA562927	Coverage (\$)	0.00
	Claim No.	S1M038JI	Excess (\$)	0.00
	Assign From		Assign Date	22/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA ACCORD (A)	c.c	2354
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MRHCP26308P020358	Colour	METALLIC SILVER
	Odometer	190850 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	MICHELIN	5 mm
	L/H Front Tyre	225/50 R17	MICHELIN	5 mm
	R/H Rear Tyre	225/50 R17	MICHELIN	4 mm
	L/H Rear Tyre	225/50 R17	MICHELIN	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS			
5. General Information				
	Accident Date	15/04/2021	Inspection Date	22/04/2021
	Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	