



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Ref: CS/UOI21005069/R1vf3e2	
			Date: 26/07/2021	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SJB 339U
	Policy No.	DHOM110165671802	Coverage (\$)	0.00
	Claim No.	M11D12642105	Excess (\$)	600.00
	Assign From	JOSEPHINE WONG	Assign Date	23/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 216I GT LED NAV	c.c	1499
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WBA2D920505E91456	Colour	GREY
	Odometer	53446 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R17	PIRELLI	6 mm
	L/H Front Tyre	205/55 R17	PIRELLI	6 mm
	R/H Rear Tyre	205/55 R17	PIRELLI	6 mm
	L/H Rear Tyre	205/55 R17	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE RECOVERED FROM FLOOD. MANY ELECTRICAL & MECHANISM PARTS FOUND DAMAGED AND CONTAMINATED BY FLOOD WATER AT THE TIME OF INSPECTION.			
5. General Information				
	Accident Date	17/04/2021	Inspection Date	23/04/2021
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks				
	A)THE MARKET VALUE IS S\$95,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	