

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21005070/Uqf3n2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924		Date:	06/05/2021	
			Code	: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	E 7255J	Veh. Inspected	SLG 7286S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10009963/JM	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	23/04/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3 SP (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JM6BM42A8G0343827	Colour	BLUE	
	Odometer	86357 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/40 ZR18	MICHELIN	6 mm	
	L/H Front Tyre	225/40 ZR18	MICHELIN	6 mm	
	R/H Rear Tyre	225/40 ZR18	MICHELIN	6 mm	
	L/H Rear Tyre	225/40 ZR18	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	21/04/2021	Inspection Date	26/04/2021	
	Survey held at	RELIABLE CARZ PTE LTD			
		8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: