

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 26 Nov 2021

Preliminary Advice

Vehicle No	: SKR7576J	Accident Date	: 18/04/2021
Make	: VOLKSWAGEN SHARAN	Policy No.	: 1001402263
Assignment Date	: 23/04/2021	Excess	: S\$1,500.00
Date of Inspection	: 23/04/2021	Est. Duration of Repair	: 14
Inspection At	: VANTAGE AUTOMOTIVE LIMITED (ALEXANDRA) 305 ALEXANDRA ROAD #02-01, VANTAGE AUTOMOTIVE CENTRE SINGAPORE 159942		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	58,508.33	(ESTIMATE \$39,126.46 + SUPPLEMENTARY \$19,381.87)
Revised Amount	:S\$	26,377.54	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	26,377.54	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	102,000.00
COE / PARF Rebate	:S\$	63,706.00
Salvage Value	:S\$	
Margin for Repair	:S\$	38,294.00

Remarks

- (X) The vehicle is economical for repair
 () The vehicle is not economical for repair
 (X) Part-by-Part repair
 () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON SUPPLEMENTARY.