

# Vantage Automotive Limited

(Division of Vantage Automotive Limited)

Business Registration No. 192600045M GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6272 8828

Fax : 6477 7398



GST Registration No. M2-0000551-1

## ESTIMATE

Estimate No. : B9 5021  
Date Estimated : 22/04/2021  
Prepared By : Andy Ooi Lee Keong

Page No. : 1 of 3

### - ESTIMATE REPAIR FOR -

Tan Kok Cheng  
114 Saraca Road

Singapore 807410

### - ACCOUNT - 24748

MSIG Insurance (Singapore) Pte Ltd  
16 Raffles Quay  
#24-01 Hong Leong Building  
Singapore 048581

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL        | MILEAGE |
|-----------|-------------------|------------|--------------|---------|
| SKR7576J  | WVWZZZ7NZHV236794 | 31/05/2017 | VOLKSWAGEN S | 0       |

### DESCRIPTION

TO CONDUCT OD CLAIM - MSIG INS. DOA.18/04/2021

VALUE

0.00

LABOUR TO REMOVE & REPLACE FRONT DOOR RH, REAR DOOR RH, ROCKER PANEL RH, CENTRE DOOR PILLAR RH, REAR FENDER RH, FRONT FENDER RH, FRONT BUMPER, REAR BUMPER & FLOOR PANEL RH.

2100 1500

3,600.00

LABOUR TO RESPRAY & PUTTY FRONT DOOR RH, REAR DOOR RH, ROCKER PANEL RH, CENTRE DOOR PILLAR RH, REAR FENDER RH, FRONT FENDER RH, FRONT BUMPER, REAR BUMPER & FLOOR PANEL RH.

1000

2,800.00

TO CONDUCT ECU PROGRAMMING CHECK & CLEAR FAULT CODES.

250

480.00

TO CONDUCT FULL WHEEL ALIGNMENT.

100

350.00

TO REMOVE & INSTALL FRONT LH SUSPENSION INSPECTION AND REPLACE DAMAGED PARTS.

X 17250?

380.00

TO REMOVE & INSTALL REAR LH SUSPENSION, REAR LH AXLE & CONTROL SYSTEM TO FACILITATE THE WORK ON REPAIR BENCH.

X 17250?

380.00

TO REMOVE & INSTALL REAR SUSPENSION, REAR AXLE AND CONTROL SYSTEM FOR INSPECTION AND REPLACE DAMAGED PARTS.

171 X

580.00

TO MOUNT VEHICLE ON REPAIR BENCH TO FACILITATE RE-ALIGNMENT OF CHASSIS ACCORDING TO SPECIFICATION. (photo)

1,680.00

TO REMOVE & INSTALL REAR HAT-TRAY, REAR SEAT, CARPET & ROOF TOP LINING TO FACILITATE THE CUTTING OF THE CENTRE, PILLAR RH, PILLAR LH & ROCKER PANEL RH.

250

1700

600.00

TO REMOVE & INSTALL FRONT & REAR RH WINDOW GLASS INCLUDING TO CONDUCT WATER LEAK TEST.

200

280.00

TO REPLACE LEATHER SEAT COVERS ON FRONT SEAT RH INCLUDING TO REMOVE AND INSTALL SEATS.

200

480.00

TO TRANSFER LOCK MECHANISM FRONT & REAR DOOR (RH), DOOR TRIM BOARD AND WINDOW REGULATOR MOTOR.

200

760.00



# Vantage Automotive Limited

Division of Vantage Automotive Limited)  
Business Registration No. 192600045M GST Registration No. M2-0000551-1  
25 Alexandra Road  
159942 Singapore  
Tel : 6272 8828  
Fax : 6477 7398



GST Registration No. M2-0000551-1

## ESTIMATE

Estimate No. : B9 5021  
Date Estimated : 22/04/2021  
Prepared By : Andy Ooi Lee Keong

Page No. : 2 of 3

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL        | MILEAGE |
|-----------|-------------------|------------|--------------|---------|
| SKR7576J  | WVWZZZ7NZHV236794 | 31/05/2017 | VOLKSWAGEN S | 0       |

| DESCRIPTION                                                             | VALUE                 |
|-------------------------------------------------------------------------|-----------------------|
| TO CHECK ELECTRICAL WIRING SYSTEM AND TO RESET AIRBAG WARNING LIGHT ON. | <del>180</del> 380.00 |
| TO REPLACE BOTH FRONT & REAR SEAT BELT TENSIONER.                       | <del>200</del> 560.00 |
| TO REPLACE ROOF TOP HEADLINING AND HEAD AIR BAG.                        | <del>250</del> 680.00 |
| TO REPLACE FRONT RH SEAT AIRBAG.                                        | <del>250</del> 680.00 |
| TO CARRY OUT BODY CAVITY PRESERVATION.                                  | <del>150</del> 270.00 |
| TO SUPPLY 2PCS TYRE - 225/50R17                                         | <del>280.00</del>     |

Total Labour 1: 15,220.00

| DESCRIPTION                                      | QTY | PRICE    | DISC | VALUE    |
|--------------------------------------------------|-----|----------|------|----------|
| FRONT BUMPER LH LOWER COVER <del>2</del> ? XAN   | 1   | 133.18   | 0.00 | 133.18   |
| FRONT DOOR RH <del>1</del> ? XAN                 | 1   | 1,411.78 | 0.00 | 1,411.78 |
| FRONT DOOR SEAL <del>1</del> ? XAN               | 1   | 175.46   | 0.00 | 175.46   |
| FRONT DOOR CHROME <del>1</del> ? XAN             | 1   | 129.37   | 0.00 | 129.37   |
| FRONT DOOR HINGES RH (UPPER) <del>1</del> ? XAN  | 1   | 53.77    | 0.00 | 53.77    |
| FRONT DOOR HINGES RH (LOWER) <del>1</del> ? XAN  | 1   | 53.77    | 0.00 | 53.77    |
| FRONT DOOR WINDOW LIFTER <del>1</del> ? XAN      | 1   | 171.48   | 0.00 | 171.48   |
| FRONT DOOR WINDOW MOTOR <del>1</del> ? XAN       | 1   | 157.75   | 0.00 | 157.75   |
| FRONT WING MIRROR HOUSING <del>1</del> ? XAN     | 1   | 529.68   | 0.00 | 529.68   |
| FRONT WING MIRROR COVER <del>1</del> ? XAN       | 1   | 60.97    | 0.00 | 60.97    |
| FRONT WING MIRROR GLASS <del>1</del> ? XAN       | 1   | 124.75   | 0.00 | 124.75   |
| REAR DOOR RH SEAL <del>1</del> ? XAN             | 1   | 292.03   | 0.00 | 292.03   |
| REAR DOOR RH CHROME <del>1</del> ? XAN           | 1   | 133.95   | 0.00 | 133.95   |
| REAR DOOR RH HINGE <del>1</del> ? XAN            | 1   | 159.90   | 0.00 | 159.90   |
| REAR DOOR RH INNER SEAL <del>1</del> ? XAN       | 1   | 197.37   | 0.00 | 197.37   |
| REAR DOOR RH WINDOW LIFTER <del>1</del> ? XAN    | 1   | 179.27   | 0.00 | 179.27   |
| REAR DOOR RH MOTOR <del>1</del> ? XAN            | 1   | 157.75   | 0.00 | 157.75   |
| REAR DOOR RH LOCK <del>1</del> ? XAN             | 1   | 382.68   | 0.00 | 382.68   |
| RR DOOR POWER LOCK MOTOR <del>1</del> ? XAN      | 1   | 334.18   | 0.00 | 334.18   |
| REAR QUARTER GLASS RH <del>1</del> ? XAN         | 1   | 291.36   | 0.00 | 291.36   |
| ROCKER PANEL WITH B-PILLAR RH <del>1</del> ? XAN | 1   | 1,011.82 | 0.00 | 1,011.82 |
| REAR DOOR TOP CHROME RH <del>1</del> ? XAN       | 1   | 142.25   | 0.00 | 142.25   |
| FRONT DOOR TOP CHROME RH <del>1</del> ? XAN      | 1   | 186.29   | 0.00 | 186.29   |
| CURTAIN ROOF AIRBAG RH <del>1</del> ? XAN        | 1   | 1,068.05 | 0.00 | 1,068.05 |
| ROOF LINING <del>1</del> ? XAN                   | 1   | 1,178.13 | 0.00 | 1,178.13 |
| A-PILLAR INNER COVER RH UPPER <del>1</del> ? XAN | 1   | 160.60   | 0.00 | 160.60   |
| A-PILLAR INNER COVER RH LOWER <del>1</del> ? XAN | 1   | 22.78    | 0.00 | 22.78    |
| FRONT SEAT AIR BAG RH <del>1</del> ? XAN         | 1   | 711.23   | 0.00 | 711.23   |
| WIRE HARNESS <del>1</del> ? XAN                  | 1   | 156.33   | 0.00 | 156.33   |
| PADDING ITEM <del>1</del> ? XAN                  | 1   | 212.44   | 0.00 | 212.44   |



# Vantage Automotive Limited

(Incorporated in Singapore)

UEN: S7000045M GST Registration No. M2-0000551-1

110 Alexandra Road

#02-01 Singapore

Tel: 6272 8828

Fax: 6477 7398



GST Registration No. M2-0000551-1

## ESTIMATE

Estimate No. : B9 5021  
Date Estimated : 22/04/2021  
Prepared By : Andy Ooi Lee Keong

Page No. : 3 of 3

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL        | MILEAGE |
|-----------|-------------------|------------|--------------|---------|
| SKR7576J  | WVWZZZ7NZHV236794 | 31/05/2017 | VOLKSWAGEN S | 0       |

| DESCRIPTION                              | QTY | PRICE    | DISC | VALUE    |
|------------------------------------------|-----|----------|------|----------|
| FRONT SEAT LEATHER RH <i>turn</i>        | 1   | 898.70   | 0.00 | 898.70   |
| FRONT SEAT RAIL RH <i>Xan</i>            | 1   | 750.19   | 0.00 | 750.19   |
| FRONT SEAT BELT RH <i>Ag</i>             | 1   | 430.46   | 0.00 | 430.46   |
| FRONT SEAT BELT LH <i>Ag</i>             | 1   | 430.46   | 0.00 | 430.46   |
| REAR SEAT BELT RH <i>not changed</i>     | 1   | 430.46   | 0.00 | 430.46   |
| B-PILLAR INNER COVER RH UPPER <i>Xan</i> | 1   | 141.99   | 0.00 | 141.99   |
| AIRBAG STICKER (RH B-PILLAR) <i>Xan</i>  | 1   | 10.86    | 0.00 | 10.86    |
| AIRBAG CONTROL UNIT MODULE <i>re</i>     | 1   | 980.07   | 0.00 | 980.07   |
| RH FRONT RIM <i>Xan</i>                  | 1   | 457.63   | 0.00 | 457.63   |
| RH REAR RIM <i>Xan</i>                   | 1   | 457.63   | 0.00 | 457.63   |
| LH FRONT RIM <i>SC</i>                   | 1   | 457.63   | 0.00 | 457.63   |
| LH REAR RIM <i>SC</i>                    | 1   | 457.63   | 0.00 | 457.63   |
| LH REAR SHOCK ABSORBER <i>Xan</i>        | 1   | 191.71   | 0.00 | 191.71   |
| LH REAR WHEEL BEARING <i>Xan</i>         | 1   | 339.49   | 0.00 | 339.49   |
| RH REAR SHOCK ABSORBER <i>Xan</i>        | 1   | 191.71   | 0.00 | 191.71   |
| RH REAR WHEEL BEARING <i>Xan</i>         | 1   | 339.49   | 0.00 | 339.49   |
| LH FRONT SHOCK ABSORBER <i>Xan</i>       | 1   | 223.75   | 0.00 | 223.75   |
| LH FRONT WHEEL BEARING <i>Xan</i>        | 1   | 299.30   | 0.00 | 299.30   |
| LH FRONT LOWER ARM <i>Xan</i>            | 1   | 297.06   | 0.00 | 297.06   |
| LH FRONT UPPER ARM <i>Xan</i>            | 1   | 300.62   | 0.00 | 300.62   |
| LH TIE ROD <i>Xan</i>                    | 1   | 58.36    | 0.00 | 58.36    |
| STEERING RACK AND PINION <i>Xan</i>      | 1   | 3,329.49 | 0.00 | 3,329.49 |
| CROSS MEMBER <i>Xan</i>                  | 1   | 908.57   | 0.00 | 908.57   |
| LH REAR KING PIN <i>Xan</i>              | 1   | 420.40   | 0.00 | 420.40   |
| LH REAR TRAILING ARM <i>Xan</i>          | 1   | 157.83   | 0.00 | 157.83   |
| RH REAR KING PIN <i>Xan</i>              | 1   | 420.40   | 0.00 | 420.40   |
| RH REAR TRAILING ARM <i>Xan</i>          | 1   | 157.83   | 0.00 | 157.83   |
| LH FRONT KING PIN <i>Xan</i>             | 1   | 386.37   | 0.00 | 386.37   |

**RIM 1762.66**

*Hp 900/10068*

*10-11 days*

*EXCESS: 1500*

*Revert*

*Resurvey before*

*paint*

*23/04/21*

*@1530*

Total Parts : 23,906.46

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer Name & Signature / Company Stamp

Date

|                |   |           |
|----------------|---|-----------|
| Labour 1       | : | 15,220.00 |
| Parts          | : | 23,906.46 |
| Labour 2       | : | 0.00      |
| Excess         | : | 0.00      |
| Total GST @ 7% | : | 2,738.85  |
| Grand Total    | : | 41,865.31 |

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

58508.33



# Vantage Automotive Limited

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777398



Car Reg No: SKR7576J

Date: 29.06.2021 \* Supp

| NO.          | Supplementary / Check Items Parts             | Part Number            | Qty | U / Price | Disc % | Ext Price          |
|--------------|-----------------------------------------------|------------------------|-----|-----------|--------|--------------------|
| 1            | LH REAR SEAT BELT <i>rec</i>                  |                        | 1   | 474.61    | 10%    | 474.61 <i>X 19</i> |
| 2            | Front RH door garnish (lower trim) <i>rec</i> | <i>RASUL</i>           | 1   | 132.00    | 10%    | 132.00 <i>X</i>    |
| 3            | REAR RH door garnish (lower trim) <i>rec</i>  | <i>29/06/21 @ 1455</i> | 1   | 203.50    | 10%    | 203.50 <i>X</i>    |
| 4            |                                               |                        |     |           |        |                    |
| 5            |                                               |                        |     |           |        |                    |
| 6            |                                               |                        |     |           |        |                    |
| 7            |                                               |                        |     |           |        |                    |
| Parts Total: |                                               |                        |     |           |        | \$810.11           |

| NO.                   | Supplementary Labour Charges | Price    |
|-----------------------|------------------------------|----------|
| 1                     |                              |          |
| 2                     |                              |          |
|                       |                              |          |
|                       |                              |          |
|                       |                              |          |
|                       |                              |          |
| Total Labour:         |                              | \$0.00   |
| Total Parts & Labour: |                              | \$810.11 |
| GST @ 7%:             |                              | \$56.71  |
| Grand Total:          |                              | \$866.82 |

|                         |                                  |                                   |                                      |
|-------------------------|----------------------------------|-----------------------------------|--------------------------------------|
| Raised By<br>Technician | Approved By<br>CSA<br><br>Syasya | Acknowledge By<br>Parts Assistant | BO Parts: Yes / No<br><br>ETA: _____ |
|-------------------------|----------------------------------|-----------------------------------|--------------------------------------|



# Vantage Automotive Limited

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777398



Car Reg No: SKR7576J

Date: 19.07.2021

| NO.          | Supplementary / Check Items Parts     | Part Number    | Qty | U / Price | Disc % | Ext Price |
|--------------|---------------------------------------|----------------|-----|-----------|--------|-----------|
| 1            | RH REAR AIR VENT <i>CRM</i>           | 7N0820952Q Y20 | 1   | \$48.71   |        | \$48.71   |
| 2            | FRONT LH SEAT BELT ADJUSTER <i>JM</i> | 3C8857819      | 1   | \$91.61   |        | \$91.61   |
| 3            |                                       |                |     |           |        |           |
| Total Parts: |                                       |                |     |           |        | \$140.32  |

*RASUC*  
12/07/21

| NO.                   |  |          |
|-----------------------|--|----------|
| 1                     |  |          |
| 2                     |  |          |
| 3                     |  |          |
|                       |  |          |
|                       |  |          |
|                       |  |          |
| Total Labour:         |  | \$0.00   |
| Total Parts & Labour: |  | \$140.32 |
| GST @ 7%:             |  | \$9.82   |
| Grand Total:          |  | \$150.14 |

|                         |                                  |                                   |                                      |
|-------------------------|----------------------------------|-----------------------------------|--------------------------------------|
| Raised By<br>Technician | Approved By<br>CSA<br><br>Syasya | Acknowledge By<br>Parts Assistant | BO Parts: Yes / No<br><br>ETA: _____ |
|-------------------------|----------------------------------|-----------------------------------|--------------------------------------|

Survey Fee:

Resurvey No. of Trip:

Date/Time, File Return to:



# Vantage Automotive Limited

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777388



Car Reg No: SKR7576J

Date: 10.05.2021

| NO. | Supplementary / Check Items Parts         | Part Number    | Qty | U / Price | Ext Price   |         |
|-----|-------------------------------------------|----------------|-----|-----------|-------------|---------|
| 1   | RH FRT DOOR                               | 7N0831056AF    | 1   |           | \$ 1,482.48 | X NN    |
| 2   | RH FRT DOOR SEAL OUTER <i>af</i>          | 7N0837701C     | 1   |           | \$ 181.05   | X NN    |
| 3   | RH FRT DOOR SEAL INNER <i>cut</i>         | 7N0867912C 9B9 | 1   |           | \$ 228.76   | * *     |
| 4   | RR RH DOOR <i>bt</i>                      | 7N0843108AP    | 1   |           | \$ 1,731.35 | * *     |
| 5   | RUBBER STOPPER UPPER <i>re</i>            | 7N0843842A     | 1   |           | \$ 35.48    | * *     |
| 6   | RUBBER STOPPER LOWER <i>re</i>            | 7N0843844A     | 1   |           | \$ 35.48    | * *     |
| 7   | CATCH PLATE UPPER <i>re</i>               | 7N0843638      | 1   |           | \$ 49.54    | * *     |
| 8   | CATCH PLATE LOWER <i>re</i>               | 7N0843640      | 1   |           | \$ 49.54    | * *     |
| 9   | DOOR SEAL W/SENSOR <i>re</i> <i>photo</i> | 7N0839718AD    | 1   |           | \$ 302.14   | X NN    |
| 10  | DOOR ROLLER GUIDE <i>bt</i>               | 7N0843398D     | 1   |           | \$ 259.34   | * *     |
| 11  | TRIM ROLLER GUIDE <i>de</i> <i>photo</i>  | 7N0868640C 82V | 1   |           | \$ 17.86    | * *     |
| 12  | DOOR SEAL LOWER <i>re</i>                 | 7N0843866A     | 1   |           | \$ 49.54    | * *     |
| 13  | RH FRT WINDOW REGULATOR <i>bt</i>         | 7N0837462J     | 1   |           | \$ 177.64   | * *     |
| 14  | RH PANEL SEAL <i>re</i>                   | 7N0809876E     | 1   |           | \$ 116.70   | * *     |
| 15  | RR RH DOOR INNER SEAL <i>X</i>            | 7N0867914G 9B9 | 1   |           | \$ 203.54   | X NN    |
| 16  | SIDE PANEL OUTER RH <i>bt</i>             | 7N0809052F     | 1   |           | \$ 1,783.98 | * *     |
| 17  | RH RR PANEL <i>X</i>                      | 7N0809642D     | 1   |           | \$ 164.16   | X NN    |
| 18  | TAIL LIGHT PANEL <i>X</i>                 | 7N0813328      | 1   |           | \$ 133.84   | X NN    |
| 19  | ROOF LINING <i>X</i>                      | 7N0867501BE6K8 | 1   |           | \$ 1,215.91 | X NN    |
| 20  | TRIM FOR SEAT BELT <i>re</i>              | 7N0867071 Y20  | 1   |           | \$ 26.18    | * *     |
| 21  | GROMMET <i>re</i>                         | 3C0867333      | 1   | 20        | \$ 0.85     | 17 *    |
| 22  | ROOF LIGHTING FRAME FRT <i>photo?</i>     | 1K0867489E Y20 | 1   |           | \$ 48.57    | X NN    |
| 23  | BOLT <i>re</i>                            | N 10549603     | 1   | 20        | \$ 0.96     | 19-20 * |
| 24  | CLIPS <i>re</i>                           | 5N0867633B     | 1   | 20        | \$ 2.41     | 48-20 * |
| 25  | SUNGLASS HOLDER <i>X</i>                  | 1K0868837G Y20 | 1   |           | \$ 56.77    | X NN    |
| 26  | SEALANT <i>re</i>                         | D 511500A2     | 1   |           | \$ 27.91    | * *     |
| 27  | PADDING FOR BACKREST <i>cut</i>           | 7N0881776AJ    | 1   |           | \$ 219.21   | * *     |
| 28  | CLIPS <i>re</i>                           | 7H0881621      | 1   |           | \$ 4.04     | X NN    |
| 29  | 2ND BENCH BACKREST LEATHER <i>X</i>       | 7N0883806EAHEG | 1   |           | \$ 1,377.37 | X NN    |
| 30  | 2ND BENCH BACKREST PADDING <i>X</i>       | 7N0883776BD    | 1   |           | \$ 166.98   | X NN    |
| 31  | BALANCE WEIGHT <i>X</i>                   | 7N0883557      | 1   |           | \$ 104.36   | X NN    |



|              |                                      |                |             |              |         |
|--------------|--------------------------------------|----------------|-------------|--------------|---------|
| 32           | POP RIVET <i>rw</i>                  | N 91121701     | <i>1</i> 20 | \$ 1.40      | 28 *    |
| 33           | LH FRT SEAT BELT <i>X</i>            | 7N2857705 RAA  | 1           | \$ 474.62    | X NN    |
| 34           | LH FRT SEAT BUCKER <i>X rw</i>       | 5N0857755H QVZ | 1           | \$ 160.00    | *       |
| 35           | RH FRT SEAT BELT <i>X</i>            | 7N2857706 RAA  | 1           | \$ 474.62    | X NN    |
| 36           | RH FRT SEAT BUCKER <i>rw</i>         | 5N0857755G QVZ | 1           | \$ 160.00    | *       |
| 37           | SIDE AIRBAG RH FRT <i>X</i>          | 6F0880242D     | 1           | \$ 726.62    | X NN    |
| 38           | SIDE AIRBAG WIRE HARNESS <i>shot</i> | 5TA971582      | 1           | \$ 163.68    | *       |
| 39           | ROOF SIDE AIRBAG <i>X</i>            | 7N0880742B     | 1           | \$ 1,176.77  | X NN    |
| 40           | 2ND BENCH SEAT BELT RH <i>rw</i>     | 7N0857806D RAA | 1           | \$ 474.62    | X NN    |
| 41           | CONTROL UNIT FOR AIRBAG <i>X</i>     | 7N0959655D 11E | 1           | \$ 1,034.88  | X NN    |
| 42           | AIRBAG SENSOR FRT <i>rw</i>          | 7N0959651      | 1           | \$ 209.92    | *       |
| 43           | AIRBAG SENSOR SIDE <i>rw</i>         | 5N0959351B     | 1           | \$ 241.31    | *       |
| 44           | CENTRE PILLAR INNER <i>bt</i>        | 7N0809884      | 1           | \$ 345.19    | *       |
| 45           | CENTRE PILLAR UPPER <i>X</i>         | 7N0809762      | 1           | \$ 31.30     | X NN    |
| 46           | NUT SQUARE <i>rw</i>                 | N 0211565      | <i>1</i> 20 | \$ 0.92      | 18.40 * |
| 47           | FRT PILLAR LOWER <i>7 photo</i>      | 7N0809204      | 1           | \$ 416.64    | X NN    |
| 48           | CENTRE PILLAR <i>bt</i>              | 7N0809220B     | 1           | \$ 740.17    | *       |
| 49           | SEAT BELT MOUNTING <i>rw</i>         | 7N0809520      | 1           | \$ 15.18     | *       |
| 50           |                                      |                |             |              |         |
| Parts Total: |                                      |                |             | \$ 17,101.78 |         |

|               |              |
|---------------|--------------|
| Total Parts : | \$ 17,101.78 |
| GST @ 7%:     | 1,197.12     |
| Grand Total:  | 18,298.90    |

|                         |             |                                   |                    |
|-------------------------|-------------|-----------------------------------|--------------------|
| Raised By<br>Technician | Approved By | Acknowledge By<br>Parts Assistant | BO Parts: Yes / No |
|                         | CSA         |                                   |                    |
|                         | Syasya      |                                   |                    |
|                         |             |                                   | ETA: _____         |



# VANTAGE AUTOMOTIVE LIMITED

(A Sime Darby Motors Company)  
Co. Regs. No. 192600045M GST Regs. No. M2-0000551-1

305 Alexandra Road  
Vantage Automotive Centre  
Singapore 159942

Service Booking: 6477 7368  
Vantage 24-Hour Assist: 6473 8588  
Fax: 6477 7300

VANTAGE AUTOMOTIVE LIMITED



## FINALIZATION REPORT

|                                                                        |                                                                                                                                                                              |                                                                                                                |                                               |                                     |
|------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------|-------------------------------------|
| <b>REPAIR ORDER NO.</b><br><b>B9 57386</b>                             |                                                                                                                                                                              | <b>Date IN</b><br><b>27/04/2021</b>                                                                            | <b>Invoice Number</b><br><br>                 | <b>Page No.</b> 1 of 3              |
| <b>Payment Term</b><br><b>30 Days From Invoice</b>                     |                                                                                                                                                                              | <b>Invoice Date</b><br><b>??</b>                                                                               |                                               |                                     |
| <b>Customer Service Advisor</b><br><b>Chua Syahirul Syazwani Irwan</b> |                                                                                                                                                                              | <b>Invoice By</b><br><b>Katherine Chong Ful Poh</b>                                                            |                                               |                                     |
| <b>CUSTOMER INFORMATION</b>                                            |                                                                                                                                                                              | <b>INVOICE TO</b> 24748                                                                                        |                                               |                                     |
| <b>Tan Kok Cheng</b><br>114 Saraca Road<br>Singapore 807410            |                                                                                                                                                                              | <b>MSIG Insurance (Singapore) Pte Ltd</b><br>16 Raffles Quay<br>#24-01 Hong Leong Building<br>Singapore 048581 |                                               |                                     |
| <b>REGISTRATION No.</b><br><b>SKR7576J</b>                             | <b>CHASSIS No.</b><br><b>VYWZZZ7NZHV236794</b>                                                                                                                               | <b>STOCK No.</b><br><b>804065</b>                                                                              | <b>REGISTRATION DATE</b><br><b>31/05/2017</b> | <b>MODEL</b><br><b>VOLKSWAGEN S</b> |
|                                                                        |                                                                                                                                                                              |                                                                                                                | <b>MILEAGE</b><br><b>67128</b>                |                                     |
| <b>CODE</b>                                                            | <b>DESCRIPTION</b>                                                                                                                                                           | <b>UNITS</b>                                                                                                   | <b>NETT</b>                                   |                                     |
| OCSLWPNP                                                               | TO CONDUCT OD CLAIM - MSIG INS. DOA.18/04/2021                                                                                                                               | 0                                                                                                              | 0.00                                          |                                     |
| OCSLWYPY                                                               | LABOUR TO REMOVE & REPLACE FRONT DOOR RH, REAR DOOR RH, ROCKER PANEL RH, CENTRE DOOR PILLAR RH, REAR FENDER RH, FRONT FENDER RH, FRONT BUMPER, REAR BUMPER & FLOOR PANEL RH. | 0                                                                                                              | 2,100.00                                      |                                     |
| OCSLWYPY                                                               | LABOUR TO RESPRAY & PUTTY FRONT DOOR RH, REAR DOOR RH, ROCKER PANEL RH, CENTRE DOOR PILLAR RH, REAR FENDER RH, FRONT FENDER RH, FRONT BUMPER, REAR BUMPER & FLOOR PANEL RH.  | 0                                                                                                              | 1,000.00                                      |                                     |
| OCSLWPNP                                                               | TO CONDUCT ECU PROGRAMMING CHECK & CLEAR FAULT CODES.                                                                                                                        | 0                                                                                                              | 250.00                                        |                                     |
| OCSLWYPY                                                               | TO CONDUCT FULL WHEEL ALIGNMENT.                                                                                                                                             | 0                                                                                                              | 100.00                                        |                                     |
| OCSLWYPY                                                               | TO MOUNT VEHICLE ON REPAIR BENCH TO FACILITATE RE-ALIGNMENT OF CHASSIS ACCORDING TO SPECIFICATION.                                                                           | 0                                                                                                              | 1,680.00                                      |                                     |
| OCSLWYPY                                                               | TO REMOVE & INSTALL REAR HAT-TRAY, REAR SEAT, CARPET & ROOF TOP LINING TO FACILITATE THE CUTTING OF THE CENTRE, PILLAR RH, PILLAR LH & ROCKER PANEL RH.                      | 0                                                                                                              | 300.00                                        |                                     |
| OCSLWYPY                                                               | TO REMOVE & INSTALL FRONT & REAR RH WINDOW GLASS INCLUDING TO CONDUCT WATER LEAK TEST.                                                                                       | 0                                                                                                              | 200.00                                        |                                     |
| OCSLWYPY                                                               | TO REPLACE LEATHER SEAT COVERS ON FRONT SEAT RH INCLUDING TO REMOVE AND INSTALL SEATS.                                                                                       | 0                                                                                                              | 200.00                                        |                                     |
| OCSLWYPY                                                               | TO TRANSFER LOCK MECHANISM FRONT & REAR DOOR (RH), DOOR TRIM BOARD AND WINDOW REGULATOR MOTOR.                                                                               | 0                                                                                                              | 200.00                                        |                                     |
| OCSLWYPY                                                               | TO CHECK ELECTRICAL WIRING SYSTEM AND TO RESET AIRBAG WARNING LIGHT ON.                                                                                                      | 0                                                                                                              | 180.00                                        |                                     |
| OCSLWYPY                                                               | TO REPLACE BOTH FRONT & REAR SEAT BELT TENSIONER.                                                                                                                            | 0                                                                                                              | 200.00                                        |                                     |
| OCSLWYPY                                                               | TO REPLACE ROOF TOP HEADLINING AND HEAD AIR BAG.                                                                                                                             | 0                                                                                                              | 250.00                                        |                                     |
| OCSLWYPY                                                               | TO REPLACE FRONT RH SEAT AIRBAG.                                                                                                                                             | 0                                                                                                              | 250.00                                        |                                     |
| OCSLWYPY                                                               | TO CARRY OUT BODY CAVITY PRESERVATION.                                                                                                                                       | 0                                                                                                              | 150.00                                        |                                     |
| <b>Sub-Total :</b>                                                     |                                                                                                                                                                              |                                                                                                                | <b>7,060.00</b>                               |                                     |



# VANTAGE AUTOMOTIVE LIMITED

(A Sime Darby Motors Company)  
Co. Regs. No. 192600045M GST Regs. No. M2-0000551-1

305 Alexandra Road  
Vantage Automotive Centre  
Singapore 159942

Service Booking: 6477 7368  
Vantage 24-Hour Assist: 6473 8588  
Fax: 6477 7300

VANTAGE AUTOMOTIVE LIMITED



## FINALIZATION REPORT

|                                     |                                                                 |                                              |                        |
|-------------------------------------|-----------------------------------------------------------------|----------------------------------------------|------------------------|
| REPAIR ORDER NO.<br><b>B9 57386</b> | Date IN<br><b>27/04/2021</b>                                    | Invoice Number<br><b>??</b>                  | Page No. <b>2 of 3</b> |
|                                     | Payment Term<br><b>30 Days From Invoice</b>                     | Invoice Date<br><b>??</b>                    |                        |
|                                     | Customer Service Advisor<br><b>Chua Syahirul Syazwani Irwan</b> | Invoice By<br><b>Katherine Chong Fui Poh</b> |                        |

\*supp!

| CODE              | DESCRIPTION                   | UNITS | NETT     |
|-------------------|-------------------------------|-------|----------|
| N 7N0831056AF     | FRONT DOOR RH                 | 1     | 1,411.78 |
| N 7N0837701C      | FRONT DOOR SEAL               | 1     | 175.46   |
| N 7N2857508AC989  | FRONT WING MIRROR HOUSING     | 1     | 529.68   |
| N 7N0839718AD     | REAR DOOR RH SEAL             | 1     | 292.03   |
| N 7N0867914G 989  | REAR DOOR RH INNER SEAL       | 1     | 197.37   |
| N 7N0809836B      | ROCKER PANEL WITH B-PILLAR RH | 1     | 1,011.82 |
| N 7N0867501BE6K8  | ROOF LINING                   | 1     | 1,178.13 |
| N 7N0881806CEHEG  | FRONT SEAT LEATHER RH         | 1     | 898.70   |
| N 7N0857806D RAA  | REAR SEAT BELT RH             | 1     | 430.46   |
| N 7N0959655D 11E  | AIRBAG CONTROL UNIT MODULE    | 1     | 980.07   |
| N 7N0601025C 8Z8  | RIM                           | 2     | 1,762.66 |
| N 7N0867912C 989  | RH FRT DOOR SEAL INNER        | 1     | 228.76   |
| N 7N0843108AP     | RR RH DOOR                    | 1     | 1,731.35 |
| N 7N0843842A      | RUBBER STOPPER UPPER          | 1     | 35.48    |
| N 7N0843844A      | RUBBER STOPPER LOWER          | 1     | 35.48    |
| N 7N0843638       | CATCH PLATE UPPER             | 1     | 49.54    |
| N 7N0843640       | CATCH PLATE LOWER             | 1     | 49.54    |
| N 7N0843398D      | DOOR ROLLER GUIDE             | 1     | 259.34   |
| N 7N0868640C 8ZV  | TRIM ROLLER GUIDE             | 1     | 17.85    |
| N 7N0843866A      | DOOR SEAL LOWER               | 1     | 49.54    |
| N 7N0837462J      | RH FRT WINDOW REGULATOR       | 1     | 177.64   |
| N 7N0809876E      | RH PANEL SEAL                 | 1     | 116.70   |
| N 7N0809052F      | SIDE PANEL OUTER RH           | 1     | 1,783.98 |
| N 7N0867071 Y20   | TRIM FOR SEAT BELT            | 1     | 26.18    |
| N 3C0867333       | GROMMET                       | 20    | 17.00    |
| N 10549603        | BOLT                          | 20    | 19.20    |
| N 5N0867633B      | CLIPS                         | 20    | 48.20    |
| N D 511500A2      | SEALANT                       | 1     | 27.91    |
| N 7N0881776AJ     | PADDING FOR BACKREST          | 1     | 219.21   |
| N N 91121701      | POP RIVET                     | 20    | 28.00    |
| N 5N0857755H OVZ  | LH FRT SEAT BUCKER            | 1     | 160.00   |
| N 5N0857755G OVZ  | RH FRT SEAT BUCKER            | 1     | 160.00   |
| N STA971582       | SIDE AIRBAG WIRE HARNESS      | 1     | 163.68   |
| N 7N0959651       | AIRBAG SENSOR FRT             | 1     | 209.92   |
| N 5N0959351B      | AIRBAG SENSOR SIDE            | 1     | 241.31   |
| N 7N0809884       | CENTRE PILLAR INNER           | 1     | 345.19   |
| N N 0211565       | NUT SQUARE                    | 20    | 18.40    |
| N 7N0809520       | SEAT BELT MOUNTING            | 1     | 15.18    |
| N 7N0809220B      | CENTER PILLAR                 | 1     | 740.17   |
| N 7N0880742B      | CURTAIN ROOF AIRBAG RH        | 1     | 1,068.05 |
| N 6F0880242D      | FRONT SEAT AIR BAG RH         | 1     | 711.23   |
| N 7N2857706 RAA   | FRONT SEAT BELT RH            | 1     | 430.46   |
| N 7N2857705 RAA   | FRONT SEAT BELT LH            | 1     | 430.46   |
| 7N0854940H GRU    | RH FRONT DOOR LOWER GARNISH   | 1     | 132.00   |
| 7N0854950H GRU    | RH REAR DOOR LOWER GARNISH    | 1     | 203.50   |
| N 7N0820952O Y20  | RH REAR AIR VENT              | 1     | 48.71    |
| N 3C8857819       | FRONT LH SEAT BELT ADJUSTER   | 1     | 91.61    |
| N A7N0857805D RAA | 2ND ROW LH SEAT BELT          | 1     | 358.60   |

Sub-Total : 19,317.54

Attending CSO : Syasya

Should you require further explanation, please reach me at 92782710



# VANTAGE AUTOMOTIVE LIMITED

(A Sime Darby Motors Company)

Co. Regs. No. 192600045M GST Regs. No. M2-0000551-1

305 Alexandra Road  
Vantage Automotive Centre  
Singapore 159942

Service Booking: 6477 7368  
Vantage 24-Hour Assist: 6473 8588  
Fax: 6477 7300



## FINALIZATION REPORT

|                                     |                                                                                                                                                |                                                                                                 |                        |
|-------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|------------------------|
| REPAIR ORDER NO.<br><b>B9 57386</b> | Date IN<br><b>27/04/2021</b><br>Payment Term<br><b>30 Days From Invoice</b><br>Customer Service Advisor<br><b>Chua Syahirul Syazwani Irwan</b> | Invoice Number<br><br>Invoice Date<br><b>??</b><br>Invoice By<br><b>Katherine Chong Ful Poh</b> | Page No. <b>3 of 3</b> |
|-------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|------------------------|

|                  |           |                                            |               |
|------------------|-----------|--------------------------------------------|---------------|
| Service Packages | 0.00      | Total Labour/Parts/Service Package Charges | S\$ 26,377.54 |
| Labour Charges   | 7,060.00  | Less Insurance Excess                      | S\$ 1,500.00  |
| Parts Charges    | 19,317.54 | GST @ 7%                                   | S\$ 1,741.43  |
| Lubricant/Misc   | 0.00      | Invoice Total Amounts                      | S\$ 26,618.97 |
|                  |           | Less Deposit/Voucher                       | S\$ 0.00      |

Computer generated invoice. No signature is required.

Amount Payable S\$ 26,618.97

We now accept fully cashless payment methods - all payments can only be made via Contactless Payment Link, Bank Transfer, NETS, PayNow and Credit Card (Visa, Masters, Google/Apple Pay and PayWave).

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





# Vantage Automotive Limited

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777398



Car Reg No: SKR7576J

RO Number: B9 57386

Date:

| NO.          | Supplementary / Check Items Parts | Part Number     | Qty | U / Price | Disc % | Ext Price |
|--------------|-----------------------------------|-----------------|-----|-----------|--------|-----------|
| 1            | 2ND ROW LH SEAT BELT <i>ACT /</i> | A7N0857805D RAA | 1   | \$358.60  | 0%     | \$358.60  |
| 2            |                                   |                 |     |           | 10%    | \$0.00    |
| 3            |                                   |                 |     |           | 10%    | \$0.00    |
| 4            |                                   |                 |     |           | 10%    | \$0.00    |
| 5            |                                   |                 |     |           | 10%    | \$0.00    |
| 6            |                                   |                 |     |           | 10%    | \$0.00    |
| 7            |                                   |                 |     |           | 10%    | \$0.00    |
| 8            |                                   |                 |     |           | 10%    | \$0.00    |
| 9            |                                   |                 |     |           | 10%    | \$0.00    |
| 10           |                                   |                 |     |           | 10%    | \$0.00    |
| Parts Total: |                                   |                 |     |           |        | \$358.60  |

| NO.                   | Supplementary Labour Charges | Price    |
|-----------------------|------------------------------|----------|
|                       |                              | \$0.00   |
|                       |                              |          |
|                       |                              |          |
|                       |                              |          |
|                       |                              |          |
|                       |                              |          |
| Total Labour:         |                              | \$0.00   |
| Total Parts & Labour: |                              | \$358.60 |
| GST @ 7%:             |                              | \$25.10  |
| Grand Total:          |                              | \$383.70 |

|                         |                               |                                   |                                      |
|-------------------------|-------------------------------|-----------------------------------|--------------------------------------|
| Raised By<br>Technician | Approved By<br>CSA<br><br>SYA | Acknowledge By<br>Parts Assistant | BO Parts: Yes / No<br><br>ETA: _____ |
|-------------------------|-------------------------------|-----------------------------------|--------------------------------------|