

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	▼	📄	✓	🖨		Find Next
---	---	---	--------	---	---	---	---	------	---	---	---	---	----------------------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref: CS/MSG21005098/Uvf3	
4 SHENTON WAY #21-01,SGX CENTRE 2			Date: 23/04/2021	
SINGAPORE 068807			Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 697P		Veh. Inspected	YP 7548K
Policy No.	1001442731		Coverage (\$)	0.00
Claim No.	255091		Excess (\$)	0.00
Assign From	CRYSTAL LEE		Assign Date	23/04/2021
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/03/2021		Inspection Date	26/04/2021
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				