

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	12 Apr 2021 17:19	Clm Veh Model Changed		[] Merimen Administrator
2	12 Apr 2021 17:19	Clm Created	Reg No: SDZ7071P. Policy No: 1900020192-01. Acct Date: 2021/04/10. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R214A0003	[I] Merimen Administrator
3	19 Apr 2021 12:03	Clm Registration Modified	Acct Time:11:49:00->11:00:00. Pol No:1900020192-01->1900020192.	[I] Low, Xianyu
4	26 Apr 2021 10:43	Clm Registration Modified	Init.Est.:>5,000 - 6,000.	[I] Low, Xianyu
5	26 Apr 2021 12:33	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
6	26 Apr 2021 12:33	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
7	26 Apr 2021 12:33	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
8	26 Apr 2021 12:33	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/05/05	[A] CELINE FONG
9	26 Apr 2021 12:33	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
10	26 Apr 2021 12:33	Clm Registration Modified	Rep:1137->200611.	[A] CELINE FONG
11	26 Apr 2021 12:33	Clm Veh Model Changed	(206234) AUDI Q8 3.0 TFSI QU TIP (A).	[A] CELINE FONG
12	26 Apr 2021 12:33	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CELINE FONG
13	26 Apr 2021 15:31	Clm Registration Modified	Excess: -> 400.00. Excess Waived: -> 1000.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Azlan, Syazairdina
14	26 Apr 2021 15:31	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
15	27 Apr 2021 10:47	Adj Rpt Initiated		[A] HUEY YON
16	27 Apr 2021 10:47	Insured Phone No Updated	[6596177366] -> [+656596177366]	[A] HUEY YON
17	27 Apr 2021 10:47	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] HUEY YON
18	27 Apr 2021 10:47	Clm Dtl Modified	JPJ Reg. Date: -> 2019/02/26.	[A] HUEY YON
19	27 Apr 2021 10:47	Clm Details Notified		[A] HUEY YON
20	27 Apr 2021 11:22	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/05/05	[A] Tan Hui Zhen
21	27 Apr 2021 11:25	Adj Mandate Request	Cur.Req:23159.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REP AIR.	[A] Tan Hui Zhen
22	27 Apr 2021 13:03	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/05/05. Mandate Remarks: Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair	[I] Lim, Kok-Chong
23	27 Apr 2021 13:03	Adj Mandate Set	Approved:22698.00:Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date From   Date To   Audit Type 

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name	Ref 1	Ref 2	Amount
-------------	-----------	-----------	----------	----------	---------	-------	-------	--------

					(Branch)			
2689440	27 Apr 2021 10:47:17	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SDZ7071P		11.00