

Stars Autoworks

160 Sin Ming Drive
#06-21 Sin Ming AutoCity
Singapore 575722
Email: starsautoworks@gmail.com

STARS RENTAL & LEASING
160 Sin Ming Drive
#05-21 Sin Ming Drive
Singapore 575722

Not Withheld
U/Sy &
Resurvey After Paint
3 days

ESTIMATE

DATE : 27/04/2021
VEHICLE NO : SJC 2464 Y
MAKE/MODEL : Honda Stream
ACC DATE : 19/04/2021

PARTICULAR	AMOUNT S\$
LIST ITEMS:	
1 1 FRONT BUMPER	CM 652.30 ✓
2 1 FRONT BUMPER FOG LAMP - LH	in 264.80 X
3 1 FRONT BUMPER FOG LAMP COVER - LH	in 65.70 X
4 1 FRONT BUMPER REINFORCEMENT	246.10 ?
5 2 FRONT BUMPER SIDE RETAINER	28.50 oil in 57.00 ✓
6 1 FRONT BUMPER TOP BEAM	95.30 ?
7 1 FRONT RADIATOR GRILLE	in 322.50 X
8 1 FRONT RADIATOR TOP PLATE	in 812.10 X
9 1 FRONT RADIATOR LOGO	in 32.90 X
10 1 FRONT HEAD LAMP (AUTO) - LH	CM 576.40 ✓
11 1 FRONT HEAD LAMP BRACKET	CM 65.70 ✓
	3,190.80
Less Discount:	20% 638.16
	2,552.64
SPECIAL NETT ITEMS:	
1 10 REAR BUMPER CLIP	5.00 in 50.00 ✓
2 5 FRONT RADIATOR GRILLE CLIP	5.00 in 25.00 X
	75.00
LABOUR CHARGES:	
1 TO CHECK WIRING	50.00 2cl
2 TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS	800.00 400cl
3 TO SPRAY PAINTING ON AFFECTED AREA	600.00 40cl
	1,450.00
GRAND TOTAL:	4,077.64

Singapore Dollars: Four Thousand And Seventy Seven And Cents Sixty Four Only.



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: