

Stars Autoworks

160 Sin Ming Drive
#06-21 Sin Ming AutoCity
Singapore 575722
Email: starsautoworks@gmail.com

STARS RENTAL & LEASING
160 Sin Ming Drive
#05-21 Sin Ming Drive
Singapore 575722

Not Withheld
U/Sy 8/1600h
Return After Paint
3 days

ESTIMATE

DATE : 27/04/2021
VEHICLE NO : SJC 2464 Y
MAKE/MODEL : Honda Stream
ACC DATE : 19/04/2021

PARTICULAR

AMOUNT S\$

LIST ITEMS:			
1	1 FRONT BUMPER	CM	652.30 ✓
2	1 FRONT BUMPER FOG LAMP - LH	in	264.80 X
3	1 FRONT BUMPER FOG LAMP COVER - LH	in	65.70 X
4	1 FRONT BUMPER REINFORCEMENT	R	246.10 X
5	2 FRONT BUMPER SIDE RETAINER	oil 10.1	57.00 ✓
6	1 FRONT BUMPER TOP BEAM	CM	95.30 ✓
7	1 FRONT RADIATOR GRILLE	in	322.50 X
8	1 FRONT RADIATOR TOP PLATE	in	812.10 X
9	1 FRONT RADIATOR LOGO	in	32.90 X
10	1 FRONT HEAD LAMP (AUTO) - LH	CM	576.40 ✓
11	1 FRONT HEAD LAMP BRACKET	CM	65.70 ✓
			3,190.80
Less Discount:		20%	638.16
			2,552.64

SPECIAL NETT ITEMS:


1	10 REAR BUMPER CLIP	5.00	ner	50.00 ✓
2	5 FRONT RADIATOR GRILLE CLIP	5.00	an	25.00 X
				75.00

LABOUR CHARGES:

1	TO CHECK WIRING	50.00	2cl
2	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS	800.00	400cl
3	TO SPRAY PAINTING ON AFFECTED AREA	600.00	40cl
			1,450.00

GRAND TOTAL: 4,077.64

Singapore Dollars: Four Thousand And Seventy Seven And Cents Sixty Four Only.



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: