

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

22/04/2021

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA VELLFIRE 2.5 - SML46B

1pc	front bumper	\$	1,812.50
1pc	front bumper centre chrome	\$	281.58
1pc	front bumper lower grille	\$	274.45
1pc	front bumper lower LH cover	\$	121.50
1pc	front bumper sponge	\$	171.45
1pc	front bumper reinforcement	\$	358.50
1pc	front centre grille base	\$	481.50
1pc	front centre grille lower garnish	\$	280.50
2pcs	front headlamp lower bracket @\$181.85	\$	363.70
			\$ 4,145.68
less 25%			
			\$ 1,036.42
			\$ 3,109.26
1pc	front number plate	s.nett \$	40.00
	wiring	\$	100.00
	spray painting	\$	600.00
	labour charges	\$	600.00
	Total		
		\$	4,449.26

