Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd

20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Clara Milah Yeo Date: 28 Apr 2021

Preliminary Advice

Insured Vehicle No : GBC2451D

TP Vehicle No : SHD3155B Accident Date : 24/04/2021 Make : HYUNDAI I40 Assignment Date : 26/04/2021

Date of Inspection : 26/04/2021 Est. Duration of Repair : 2

Inspection At : COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

59 LOYANG DRIVE SINGAPORE 508969

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 2,214.12 |
|-----------------------------|------|----------|
| Revised Amount | :S\$ | 1,655.80 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 1,655.80 |
| | | |
| Lump Sum Repair | :S\$ | 1,300.00 |

Total Loss Consideration

| New for Old Value | :S\$ |
|--------------------|------|
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

| (|) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. |
|---|---|---------------------------------------------------------------------------------------------------------------------------------------------|
| (|) | The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. |
| (|) | Other comments : |