

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	26 Apr 2021 16:41	Clim Veh Model Changed	(201015) NISSAN CABSTAR 3.0 (M).	[R] Kon Yin Siew
2	26 Apr 2021 16:41	Clim Created	Reg No: GBD9805R. Policy No: DMCVSNW00060492000. Acct Date: 2021/04/22. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Goldbell Engineering Pte Ltd (Tuas)	[R] Kon Yin Siew
3	26 Apr 2021 17:00	Clim Submitted	4550.03.	[R] Kon Yin Siew
4	27 Apr 2021 08:27	Clim Registration Modified	Excess: -> 500.00.	[I] Irene Tay Hui Ping
5	27 Apr 2021 08:27	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):PLEASE SURVEY AND REVERT	[I] Irene Tay Hui Ping
6	27 Apr 2021 08:27	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/05/06	[I] Irene Tay Hui Ping
7	27 Apr 2021 08:27	Adj Mandate Set	Approved:0.00.	[I] Irene Tay Hui Ping
8	27 Apr 2021 09:13	Assignment 1st Accessed		[A] LEE SU THING
9	27 Apr 2021 13:57	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] LEE SU THING
10	28 Apr 2021 15:47	Adj Rpt Initiated		[A] SHIAU CHAN
11	28 Apr 2021 15:48	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/05/06	[A] SHIAU CHAN
12	28 Apr 2021 15:49	Adj Mandate Request	Cur.Req:2684.83:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPA IR.	[A] SHIAU CHAN
13	30 Apr 2021 09:26	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/05/06	[I] Tan Kah Leong
14	30 Apr 2021 09:26	Adj Mandate Set	Approved:2684.83.	[I] Tan Kah Leong

Date From
 Date To
 Audit Type

ACTIVITY

[27/04/2021 09:20] LEE SU THING:
 Please be informed that vehicle not in the workshop, repairer will arrange.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2689259	26 Apr 2021 16:41:17	OD/TP Case (Repairer)	Motor	Goldbell Engineering Pte Ltd (Tuas)	Goldbell Engineering Pte Ltd (Tuas)	GBD9805R		xx.xx
2690057	28 Apr 2021 15:47:09	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBD9805R		11.00

