

Our Job Ref No : 305465429
Date : 28.04.21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. : SHA8317J CCPL

23/04/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SMR7609A

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%

Final Lumpsum Repair cost

\$1,500.00

3. Estimated normal period for repairs: 1 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :

Name : MS. LOKE YY

Tel : 62148355

Fax : 65468156

Signature :

Name :

Date :

For Official Use Only

| Item | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|--|-----------------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day | | YES | | |
| 2. Loss of Income Paid | | NO | | |
| 3. Survey Fees | | | | |
| 4. LTA Search Fee | \$7.49 / \$2.00 | | | |
| 5. Medical Fees (on behalf of driver, if applicable) | | | | |
| 6. Overrun | | | | |

Remarks:

COMFORT DELGRO
ENGINEERING

VEHICLE I SHA8317J
NTUC
305465429

TYPE OF C: TP
SURVEY BY: LKK/ NAZ
DATE : 28/04/2021

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

| DESCRIPTION | QTY | ESTIMATE | \$ | REMARKS |
|---------------------------|-----|----------|------------|-----------------------|
| REAR BUMPER COVER | 1 | | \$499.90 | SEE ATTACHED PHOTO |
| REAR BUMPER REINFORCEMENT | 1 | | \$318.80 | SEE ATTACHED PHOTO |
| COVER REAR FLOOR | 1 | | \$232.00 | SEE ATTACHED PHOTO |
| REAR BUMPER RUBBER MAT | 1 | | \$50.00 | SEE ATTACHED PHOTO |
| PANEL BEATING | 1 | | \$350.00 | DISMANTLE AND REPLACE |
| | | | \$1,450.70 | |
| | | | | |
| | | | | |

✓ CRK
✓ DD
✓ DEF
✓ NEC
✓ NEC

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA8317J

DOA:23.04.2021

Date: 26.04.2021

Make : Toyota

Insurance: NTUC

Model : Prius (G4A)

MVA: MS. LOKE YY

| Qty | Parts Description / Labour | Type | Unit Price | Amount |
|-----|-----------------------------|------|------------|------------------------------|
| 1 | REAR BUMPER | | | CRK \$499.90 XSVL |
| 10 | REAR BUMPER CLIPS | | | \$22.00 XSVL |
| 1 | REAR BUMPER LOWER COVER | | | \$552.60 /DEF |
| | SUB TOTAL | | 1,553.3 | \$1,074.50 |
| | LESS 25% | | | \$268.63 |
| | DISCOUNTED TOTAL | | 1,164.98 | \$805.88 |
| | | | | |
| 1 | REAR REVERSE SENSOR | | | \$135.70 XSVL |
| 1 | REAR BUMPER MAT | | | NEC \$50.00 XNN |
| | | | | \$185.70 |
| | Labour Charge | | | |
| | PANEL BEATING | | | /350 \$400.00 XNN |
| | SPRAY PAINTING CHARGE | | | /250 \$300.00 XNN |
| | REMOVE/REFIX REVERSE SENSOR | | | /30 \$60.00 XNN |
| | TUFF KOTE | | | /40 \$50.00 XNN |
| | TOTAL LABOUR | | | \$810.00 |
| | ESTIMATE TOTAL | | | \$1,801.58 |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ CKX 26/4/2021 1330
L/S

1 DAY
AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: