

REPAIR ESTIMATE*

VEHICLE NO SH6285M

DATE 24.04.21

MAKE :

MODEL : HYUNDAI IONIQ G3

CHIANG /NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$430.90
1	RADIATOR GRILLE			\$1,409.10
1	FRONT BUMPER CENTRE MOULDING			\$368.50
1	FRONT HEADLAMP ASSY LH			\$1,993.65
1	FRONT BUMPER GRILLE LH			\$186.90
1	FRONT DAY LIGHT LH			\$642.50
1	FRONT BUMPER LIP			\$285.10
1	FRONT BUMPER CENTRE MOULDING			\$368.50
				\$5,685.15
				20.00%
				\$1,137.03
				DISCOUNTED TOTAL
				\$4,548.12
				#REF!
	Labour Charge			
	Panel Beating			\$800.00
	Spray Paint			\$600.00
	Check lighting			\$60.00
				\$1,460.00
				TOTAL LABOUR
				\$6,008.12
				ESTIMATE TOTAL
<p>NAZ LKK</p> <p>27/4/2021 1445</p> <p>PR</p> <p>2 DAYS</p> <p>CHECK ITEM (PHOTO)</p> <p>BY PAINT (PHOTO)</p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: