

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: CHINA TAIPING	DATE	: 26/04/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: TP CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMQ2877E		
MODEL	: HYUNDAI AVANTE 1.6		Justin.
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 23-Apr-21
		TIME	: 1735HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dehnd</i>	1	\$ 630.00	\$ 630.00
2	REAR BUMPER LOWER LID <i>Canhd</i>	1	\$ 420.00	\$ 420.00
3	REAR BUMPER RETAINER <i>Ken</i>	2	\$ 59.60	\$ 119.20
4	REAR BUMPER REFLECTOR <i>Ken</i>	2	\$ 160.00	\$ 320.00
5	REAR BUMPER REINFORCEMENT <i>Canhd</i>	1	\$ 422.00	\$ 422.00
6	REAR BUMPER REINFORCEMENT BRACKET <i>Ken</i>	2	\$ 180.60	\$ 361.20
7	NUMBER PLATE LAMP(SET) <i>Ken</i>	1	\$ 120.00	\$ 120.00
8	REAR END PANEL <i>Regis</i>	1	\$ 577.30	\$ 577.30
9	REAR END PANEL TOP GARNISH <i>Ken Ken</i>	1	\$ 180.10	\$ 180.10

TOTAL PRICE \$ 3,149.80

LESS 20% \$ 629.96

SUB TOTAL PRICE \$ 2,519.84

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Dented</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP(SET) <i>Ken</i>	1	\$ 20.00	\$ 20.00
3	REAR END PANEL INSULATION SEALANT <i>Ken</i>	1	\$ 100.00	\$ 100.00
4	REAR END PANEL TOP GARNISH CLIPS(SET) <i>X4</i>	1	\$ 20.00	\$ 20.00

5	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	<i>200</i>
			<i>270</i> TOTAL	\$ 410.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	<i>400</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	<i>400</i>	
3	TO APPLY RUST PROOFING AND TUFF COAT	\$ 150.00	<i>50</i>	
4	WIRING CHECK	\$ 60.00	<i>30</i>	
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 120.00	<i>X</i>	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	<i>50</i>	
TOTAL		\$2,450.00		<i>930</i>

ESTIMATE REPORT

TOTAL PARTS COST : \$ 2,929.84
 TOTAL LABOUR COST : \$ 2,450.00
 TOTAL REPAIR COST : \$ 5,379.84

Adrian Ling,
L/S 26/04/21
03 Days.

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

total: 2284.56

PART BY PART / LUMP SUM :
 NO OF DAYS :

L/S: 1.8k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: