Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

Azlan, Syazairdina

Attn:

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Date: 29 Apr 2021

Preliminary Advice

Vehicle No : SMX4205U Accident Date : 21/04/2021 Policy No. : 7210002868 Make : AUDI Q3 Assignment Date : 28/04/2021 Excess : S\$0.00 Date of Inspection : 27/04/2021 Est. Duration of Repair : 4

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1 SINGAPORE 408699

55 UBI ROAD 1

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,339.00
Revised Amount	:S\$	2,808.00
Check Items (Estimated)	:S\$	250.00
Total	:S\$	3,058.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 165,000.00

 COE / PARF Rebate
 :S\$ 70,743.00

Salvage Value :S\$

Margin for Repair :S\$ 94,257.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :