

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SMRT AUTOMOTIVE SERVICES PTE LTD		Ref:	CS/SMR21005237/Btf3
60 WOODLANDS INDUSTRIAL PARK		Date:	28/04/2021
E4SINGAPORE 757705		Code:	SMR
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 780B	Veh. Inspected	SKH 4142A
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/04/21/2067	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	28/04/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/04/2021	Inspection Date	07/05/2021
Survey held at	8 Kaki Bukit Ave 4 #01-50, Premier @ Kaki Bukit		
Repairer	FC GARAGE		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			