



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: YVONNE ANG			Ref: CS3/ASM21005252/Guce2 Date: 10/05/2021 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SFB 7222Z	Veh. Inspected	SLT 4781E
	Policy No.		Coverage (\$)	0.00
	Claim No.	S1M038YU	Excess (\$)	0.00
	Assign From	YVONNE ANG	Assign Date	28/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 5 2.0	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JM6CW1071H0127377	Colour	SILVER
	Odometer	309078 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	DUNLOP	6 mm
	L/H Front Tyre	205/55 R16	DUNLOP	6 mm
	R/H Rear Tyre	205/55 R16	DUNLOP	6 mm
	L/H Rear Tyre	205/55 R16	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
	Accident Date	27/04/2021	Inspect Date / Time	28/04/2021 (05:00 PM)
	Survey held at	10 KAKI BUKIT ROAD 2 #01-29		
	Repairer	MIRAGE AUTOMOTIVE SERVICES		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	

Report Ref No. CS3/ASM21005252/Guce2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.