

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	27 Apr 2021 16:34	Clim Veh Model Changed		[] Merimen Administrator
2	27 Apr 2021 16:34	Clim Created	Reg No: SKK8337M. Acct Date: 2021/04/26. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Lt d. (SG). Ins.Status => Notification. Created from SAS:SP0R214R0001	[I] Merimen Administrator
3	29 Apr 2021 11:55	Clim Registration Modified	Init.Est.: -> 5,000 - 6,000.	[I] Low, Xianyu
4	29 Apr 2021 11:55	Clim Veh Model Changed	(203438) AUDI Q3 1.4 TFSI (A).	[I] Low, Xianyu
5	29 Apr 2021 17:34	Clim Registration Modified	Setl.Type: 3->0. Claim Type: SC->OD.	[] CELINE FONG
6	29 Apr 2021 17:34	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
7	29 Apr 2021 17:34	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
8	29 Apr 2021 17:34	Adj Next Rpt Changed	Next Rpt: Final Rpt. Due Date: 2021/05/10	[A] CELINE FONG
9	29 Apr 2021 17:34	Adj Mandate Set	Approved: 0.00. Reinsp: Adj decides.	[A] CELINE FONG
10	29 Apr 2021 17:34	Clim Registration Modified	Rep: 1137->200611.	[A] CELINE FONG
11	29 Apr 2021 17:35	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CELINE FONG
12	30 Apr 2021 09:59	Adj Rpt Initiated		[A] HUEY YON
13	30 Apr 2021 09:59	Clim Dtl Modified	Claim Conclusion: -> 3.	[A] HUEY YON
14	30 Apr 2021 09:59	Clim Dtl Modified	JPJ Reg. Date: -> 2020/08/25.	[A] HUEY YON
15	30 Apr 2021 09:59	Clim Details Notified		[A] HUEY YON
16	30 Apr 2021 10:45	Adj Im. Advice Submitted	Next Rpt: Final Rpt. Due Date: 2021/05/10	[A] SHIAU CHAN
17	30 Apr 2021 10:46	Adj Mandate Request	Cur. Req: 26791.00: DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REP AIR.	[A] SHIAU CHAN
18	06 May 2021 09:59	Clim Registration Modified	Excess: -> 400.00. Excess Waived: -> 400.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Abu Kassim, Noor Mariesa
19	06 May 2021 09:59	Label Added	(20226): Coverage Confirmed.	[A] Merimen Administrator
20	06 May 2021 11:30	Adj Next Rpt Changed	Next Rpt: Final Rpt. Due Date: 2021/05/10. Mandate Remarks: Vehicle may commence repair (Labour #5 to revise to \$1000 - Lock Carrier not confirm) Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before pai	[I] Lim, Kok-Chong
21	06 May 2021 11:30	Adj Mandate Set	Approved: 17366.00: Vehicle may commence repair (Labour #5 to revise to \$1000 - Lock Carrier not confirm) Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and P	[I] Lim, Kok-Chong

Date From



Date To



Audit Type

None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2690577	30 Apr 2021 09:59:32	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKK8337M		11.00