

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0376/2021/HR
DATE : 30-Apr-21
WIP : 25384

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 4/5/2021
YOUR INSURED VEH NO : SKD 5366 K

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR HAN KWANG SIEW, ROGER
ADDRESS : 213 PASIR RIS STREET 21
#05-202
SINGAPORE 510213
TELEPHONE : HP +65 96633105
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO :
VEHICLE NO : **SJT 296 P**
MODEL CODE : A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 29/3/2019
ENGINE NO : CVK 077267
CHASSIS NO : WAUZZZF40KA043906
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Apr-21
PLACE OF ACCIDENT : NEAR 2 BAYFRONT AVE

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJT 296 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY & FRONT PARKING AID	S/N \$ 480.00	X.
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT DAMAGES.	S/N \$ 700.00	560
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR BONNET, LHS FRONT FENDER AND LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$ 3,850.00	1500
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, LHS REAR DOOR, LHS WING MIRROR COVER, DOOR HANDLES AND LHS REAR FENDER.	\$ 5,600.00	1850 3 x 550 = 1650 Handle x 2 = 100 x 2 = 200
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	\$ 280.00	✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 11,102.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJT 296 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>New</i>	1	\$ 1,787.00	X	
2	FRONT BUMPER FIXING PARTS	1	\$ 587.00	X	
3	FRONT BUMPER AIR GUIDE - LH	1	\$ 63.00	X	
4	FRONT BUMPER SECURING STRIP	1	\$ 36.00	X	
5	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 135.00	X	
6	FRONT BUMPER GUIDE SECTION - LH	1	\$ 36.00	X	
7	FRONT DOOR - LH <i>Distorted</i>	1	\$ 3,192.00	✓	
8	FRONT DOOR OUTER SEAL - LH <i>New</i>	1	\$ 205.00	✓	
9	FRONT DOOR BONDING AGENT	1	\$ 49.00	?	
10	FRONT DOOR CLEANING SOLUTION	1	\$ 68.00	?	
11	FRONT DOOR APPLICATOR <i>New</i>	1	\$ 8.00	+	
12	FRONT DOOR CATCH	1	\$ 105.00	?	
13	FRONT DOOR HANDLE TRIM PLATE <i>Regr</i>	1	\$ 88.00	X	
14	FRONT DOOR HOUSING	1	\$ 8.00	+	
15	FRONT DOOR MOUNTING BAR <i>New</i>	1	\$ 164.00	+	
16	FRONT MIRROR - LH <i>New</i>	1	\$ 1,089.00	+	
17	REAR DOOR - LH <i>Dented</i>	1	\$ 3,192.00	✓	
18	REAR DOOR OUTER SEAL - LH <i>New</i>	1	\$ 205.00	✓	
19	REAR DOOR BONDING AGENT	1	\$ 49.00	?	
20	REAR DOOR CLEANING SOLUTION	1	\$ 68.00	?	
SUB TOTAL SPARE PARTS			\$ 11,134.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJT 296 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR APPLICATOR <i>free in</i>	1	\$ 8.00	✓
22	REAR DOOR SEALING STRIP	1	\$ 17.00	✗
23	REAR DOOR CATCH ?	1	\$ 120.00	?
24	REAR DOOR WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 240.00	✓
25	LHS REAR RIM <i>cut</i>	S/N	TBC	✓
26	SUNDRIES ?	\$	250.00	?
TOTAL SPARE PARTS		:	\$ 11,769.00	
TOTAL LABOUR CHARGES		:	\$ 11,102.00	
GRAND TOTAL		:	\$ 22,871.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *04/05/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorized, 06 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT