

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	✓	🖨	Find Next
---	---	---	--------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CS/CTI21005308/R1qf3 Date: 29/04/2021 Code: CTI	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.			Veh. Inspected	YN 8716X
Policy No.	DMCVSNW00066832000		Coverage (\$)	0.00
Claim No.	SNM21D201713/C01/TANKL		Excess (\$)	450.00
Assign From	MERIMEN (TAN KAH LEONG)		Assign Date	29/04/2021
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/03/2021		Inspection Date	30/04/2021
Survey held at	GOLDBELL ENGINEERING PTE LTD 10 TUAS AVE 18 SINGAPORE 638894			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				