

AAD2104-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5177A

Not Authorized
Perjury B4 paint

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

27 APR 2021

SHD5177A

JTDKB3FU703078482

TOYOTA

PRIUS

27/04/2021

AIG

19/12/2018

- PART**
- 1 COVER, FRONT BUMPER
 - 1 GRILLE SUB-ASSY, RADIATOR
 - 1 GRILLE, RADIATOR, LOWER NO.1
 - 1 HOOD SUB-ASSY
 - 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
 - 1 ABSORBER, FRONT BUMPER ENERGY
 - 1 RETAINER, REAR BUMPER SIDE, LH
 - 1 BRACKET, FRONT BUMPER SIDE, LH
 - 1 UNIT, HEADLAMP, LH
 - 1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1
 - 1 LAMP ASSY, FOG, LH
 - 1 FENDER SUB-ASSY, FRONT LH

LIST		
\$	Buc Lin	516.00 ✓
\$	Sn	346.00 X
\$	Sn	170.10 X
\$	R	983.10 X
\$	R	716.60 X
\$	Sn	79.60 X
\$	Dir	116.50 ✓
\$	Dir	59.30 ✓
TOTAL \$	cm	1,781.10 ✓ 2637.60
\$	Sn	960.50 X
\$	Sn	951.40 X
\$	R	977.80 X
TOTAL \$		7,658.00
25% \$		2,828.00
\$		8,484.00

Special Nett

- 1 FRONT FENDER EMBLEM LH
- 1 FRT FENDER CLIP
- 1 BONNET CLIP
- 1 FRONT NUMBER PLATE WITH MOULDING
- 1SET FRONT FENDER LINER CLIP
- 1SET FRONT BUMPER CLIP

\$	nn	150.00 X
\$	nn	65.00 X
\$	nn	70.00 X
\$	Sn	200.00 X
\$	nn	75.00 X
\$	nn	90.00 50.00
TOTAL \$		650.00

TOTAL PARTS \$ 9,530.50

LABOUR

AAD2104-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5177A

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	3001
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn 240.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	4401
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
TOTAL	\$	4,380.00	
Over All Total	\$	13,514.00	

(PART-BY-PART) Repair Days**20 days****2 days****LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: