

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 26/04/2021

TP Veh Reg No: SFU2220L

Estimate No: ES2190439/AMK

Date: 11 May 2021

Policy No: 5116951391

Veh Reg No: SJJ8289K

Make/Model: TOYOTA C-HR 1.2

Chassis No: JTNKY3BX901006432

Engine No: 8NRU174077

Reg. Date: 16/05/2018

Estimate Repair Cost to Vehicle No :SJJ8289K

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT BUMPER	397.60	1 PC	397.60	✓
2 FRONT BUMPER LOWER BUMPER	515.40	1 PC	515.40	✓
3 FRONT BUMPER LH SIDE RETAINER	118.90	1 PC	118.90	✓
4 FRONT BUMPER CLIP	4.50	6 PC	27.00	✓
5 FRONT BUMPER PDC SENSOR	392.80	1 PC	392.80	✓
6 HEADLAMP LH	4,536.00	1 PC	4,536.00	✓
			5,987.70	
		Less 25%	1,496.93	4,490.78
Labour				
7 REMOVE & REFIX FRT BUMPER & ATTACHMENTS,GRILLE,LH HEADLAMP;KNOCKING & REPAIR FRT PANEL & REALIGN THE SAME	400.00	1 LA	400.00	2500
8 PUTTY & RESPRAY FRT BUMPER & PARKING SENSORS,FRT LH FENDER & ALL AFFECTED AREAS	500.00	1 LA	500.00	3000
			900.00	900.00
			Total	S\$ 5,390.78
			Add GST @ 7%	377.35
			Total Amount Payable	S\$ 5,768.13

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

Dorlyn

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: