



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD	Ref: CS3/AIG21005320/R1tf3
78 SHENTON WAY #09-16	Date: 30/04/2021
AIG BUILDING	
SINGAPORE 079120	Code: AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SCV 988Z	Veh. Inspected	SKH 2564D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	DIVYASHNI SUBRAMANIAM	Assign Date	30/04/2021

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/04/2021	Inspection Date	30/04/2021
Survey held at	CAR LABORATORIES PTE LTD NO. 1 BUKIT BATOK CRESCENT #04-56 WCEGA PLAZA SINGAPORE 658064		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.