# Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Adeline Chng Pei Wen Date: 04 May 2021

## **Preliminary Advice**

Vehicle No : XE1401J Accident Date : 21/04/2021

Make : MITSUBISHI FUSO Policy No.

DMCVSNW00007762100

Assignment Date : 30/04/2021 Excess : S\$3,000.00

Date of Inspection : 30/04/2021 Est. Duration of Repair : 12

Inspection At : AAK LOGISTICS SERVICES PTE LTD (PENJURU)

4 PENJURU CLOSE SINGAPORE 608574

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,000.00
Revised Amount	:S\$	0.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value	:S\$
-------------------	------

 Pre-Accident Value
 :S\$ 75,000.00

 COE / PARF Rebate
 :S\$ 20,507.00

Salvage Value :S\$

Margin for Repair :S\$ 54,493.00

#### Remarks

( )	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	lly
		let us have your authorisation.	

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Pending estimate breakdown from repairer.