

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 24 May 2021

Preliminary Advice

Vehicle No	: XE1401J	Accident Date	: 21/04/2021
Make	: MITSUBISHI FUSO	Policy No.	: DMCVSNW00007762100
Assignment Date	: 30/04/2021	Excess	: S\$3,000.00
Date of Inspection	: 30/04/2021	Est. Duration of Repair	: 14
Inspection At	: AAK LOGISTICS SERVICES PTE LTD (PENJURU) 4 PENJURU CLOSE SINGAPORE 608574		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	41,174.05
Revised Amount	:S\$	27,707.29
Check Items (Estimated)	:S\$	5,715.01
Total	:S\$	33,422.30
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	20,507.00
Salvage Value	:S\$	
Margin for Repair	:S\$	54,493.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :