

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 1628U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TORN	522.50	522.50
2	FRONT BUMPER SIDE HOLDER @\$46.00	N/S DAMAGED	92.00	46.00
1	FRONT LH HEADLAMP	NOT NECESSARY	577.00	-
1	FRONT LH FENDER	DENTED	480.20	480.20
1	FRONT LH FENDER INNER SHIELD	TORN	83.30	83.30
1	FRONT LH FENDER MUD FLAP	DEFORMED	115.00	115.00
1	FRONT LH DOOR	DENTED	1,141.80	1,141.80
1	FRONT LH KNUCKLE ARM	DAMAGED	381.20	381.20
1	FRONT LH KNUCKLE ARM BEARING	DAMAGED	124.40	124.40
1	FRONT LH LOWER ARM	BENT	337.50	337.50
1	FRONT LH SHOCK ABSORBER	BENT	368.30	368.30
1	FRONT LH DRIVE SHAFT	NOT NECESSARY	1,069.00	-
1	STEERING RACK ASSY	BENT	2,056.80	1,573.00
1	LINKAGE	NOT NECESSARY	80.10	-
	LESS 20% DISCOUNT		-1,485.82	-1,034.64
			5,943.28	4,138.56
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	SET FRONT LH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	60.00	30.00
1	FRONT LH SPORT RIM (SN)	CUT	680.00	400.00
1	FRONT LH TYRE (SN)	NOT NECESSARY	380.00	-
			1,180.00	460.00
	<u>LABOUR</u>			
	TO CHECK WHEEL ALIGNMENT.		100.00	80.00
	REMOVE & REINSTALL FRONT SUSPENSION.		500.00	220.00
	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.		1,300.00	500.00
	RESPRAY PAINTING.		1,200.00	600.00

Report Ref No. CS/SMO21005328/AUvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TUFF KOTE.		100.00	40.00
			3,200.00	1,440.00
	GRAND TOTAL		10,323.28	6,038.56

RECOMMENDED COST OF LUMP SUM REPAIRS	4,800.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/SMO21005328/AUvf3n2

CHUA KANG SENG

Licensed Appraiser