

GBC 7920J

PARTS				S/N		LABOUR	SUPP (PARTS)	
	\$1,455.10	\$0.00	\$0.00		\$500.00		\$250.00	\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$450.00	\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$30.00	\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00	0%
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00	<u>\$0.00</u>
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00	SUPP (SN)
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00		\$500.00		<u>\$730.00</u>	<u>\$0.00</u>
	\$0.00	\$0.00	\$0.00					
	\$0.00	\$0.00	\$0.00					
	\$0.00	\$0.00	\$0.00					SUPP(LABOUR)
	\$0.00	\$0.00	\$0.00					
	\$0.00	\$0.00	\$0.00					\$0.00
	\$0.00	\$0.00	\$0.00					\$0.00
	\$0.00	\$0.00	\$0.00					\$0.00
	\$0.00	\$0.00	\$0.00					<u>\$0.00</u>
	\$0.00	\$0.00	\$0.00					
	\$0.00	\$0.00	\$0.00					
	\$0.00	\$0.00	\$0.00					
	\$0.00	\$0.00	\$0.00					
	\$0.00	\$0.00	\$0.00					
	\$0.00	\$0.00	\$0.00					
	\$0.00	\$0.00	\$0.00					
	\$0.00	\$0.00	\$0.00					
	\$0.00	\$0.00	\$0.00					
	\$0.00	\$0.00	\$0.00					
	\$0.00	\$0.00	\$1,455.10					
	\$0.00	\$0.00						
	\$0.00	\$0.00	\$1,455.10					
	\$0.00	\$0.00	75%					
	\$0.00	\$0.00	<u>\$1,091.33</u>					

TOTAL			\$0.00
	\$1,091.33		\$0.00
	\$500.00		\$0.00
	\$730.00		<u>\$0.00</u>
SUPP	\$0.00	<u>TOTAL SUPP</u>	<u>\$0.00</u>
P/P	<b>\$2,321.33</b>	MAKE / MODEL	T.HIACE - 2982cc
	\$2,321.33	MARKET VALUE	\$24,000.00
	80%	LTA REBATE	\$17,452.00
	\$1,857.06	NETT VALUE	\$6,548.00
L/S	<b>\$1,800.00</b>	RED	<b>\$3,300.20</b>
		TOTAL TP EST	<u>\$5,100.20</u>
		REPAIR DAYS	<u>4</u>
		REMARKS	