



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21005372/Euf3e2	
			Date: 14/05/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMB 5044B	Veh. Inspected	PD 8886Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/04/21/1052	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	03/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	SCANIA KIB4X2	c.c	11705	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	YS2K4X20001910150	Colour	MULTI COLOUR	
Odometer	105292 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	YOKOHAMA	4 mm	
L/H Front Tyre	295/80 R22.5	YOKOHAMA	4 mm	
R/H Rear Tyre	295/80 R22.5 (D)	YOKOHAMA	4/4 mm	
L/H Rear Tyre	295/80 R22.5 (D)	YOKOHAMA	4/4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/04/2021	Inspection Date	06/05/2021	
Survey held at	566 woodlands road (mandai estate) s728697			
Repairer	CONNECT3			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			14 Working Days	