

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBD505R170602

Estimate**Customer****Name:** AIG Asia Pacific Insurance Pte Ltd**Address:** Motor Claims Department

78 Shenton Way #07-16

AIG Building

Singapore 079120

Date:

30-04-21

Vehicle No:

GBD505R

Model/Make: Mitsubishi Canter

FEA01BR2DEB (CBU)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Rh Signal Lamp To check all wiring & electrical component for proper function Labor for Replacing Parts Etc	\$ 313.60 \$ 30.00 \$ 120.00	80

Total Parts & Labour of estimate for damaged vehicle

\$ 463.60

Total amount in Lump Sum Basis for repaired vehicle**SDLS:**

M/s HSIAD TONG

Not Authorized

Lulu

4/5/21

1 day

P/P \$ 315.20



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: