



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLP1		Ms Tay Hong Chin Regina (Zheng Hongzhen Regina) 17 King's Close Singapore 268194 Mobile: 97717875		
			Document No. 0				
			Document Date 03/05/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ASU60R	ANTMT E1	20/08/2020	SMU9917G	0	61794	72/DS/SMU9917G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTEZB3GH00J005722		8ARZ201029	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI TP INS:LONPAC INSURANCE TP VEH:GBB2666G DATE OF ACC:01.05.2021				50	100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100	200.00
3	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR					180.00
4	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST					122.40
5	B	BP-LAB2 REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE. R/I REAR REVERSE SENSOR TO FAC REPAIR					540.00
6	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				360	720.00
7	B	BP-LAB2 R/I TAILGATE SPOILER TO FAC REPAIR					135.00
8	B	BP-LAB2 REPLACE TAILGATE GLASS					462.00
9	L	BP-LPO SUPPLY REGN PLATE (PO#)					80.00
10	L	BP-LPO SUPPLY 3M SOLAR FILM					480.00
11	B	BP-ECU2 TO RESET ECU AND REPROGRAMME					180.00
12	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				1440	3600.00
13	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				1180	3540.00
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd					Tanji 97717875 WP 45/210 1175 Resurvey before paint Less 6 DAYS Amount Due		
Please acknowledge receipt of vehicle		Parts	Labour		Sublet		
		Lubrication/Fluid	Others				

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1	Ms Tay Hong Chin Regina (Zheng Hongzhen Regina)				
		Document No. 0	17 King's Close				
		Document Date 03/05/2021	Singapore 268194 Mobile: 97717875				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ASU60R	ANTMT E1	20/08/2020	SMU9917G	0	61794	72/DS/SMU9917G
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTEZB3GH00J005722	8ARZ201029	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
14	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION				366.36	183.80.183.18
15	S	BP-SUBLET TO REMOVE AND REFIT REAR POWER TAILGATE & KICK SENSOR				360.00	nn X 180.
16	1	T52159-48933 COVER, RR BUMPER	1.00	904.00		904.00	de ✓
17	2	T52169-48100 COVER, RR BUMPER,	1.00	466.00		466.00	de ✓
18	3	S52161-0K040 PIECE, RR BUMPER	10.00	4.10		41.00	nee ✓
19	4	T52155-48050 SUPPORT, RR BUMPER	1.00	82.70		82.70	nee ✓
20	5	T52156-48050 SUPPORT, RR BUMPER	1.00	82.70		82.70	X
21	6	T52615-48230 ABSORBER, RR BUMPER	1.00	122.60		122.60	? X
22	7	T58307-48120 PANEL SUB-ASSY, BODY	1.00	1006.40		1006.40	? X
23	8	T64716-48020 C0 COVER, DECK TRIM, RR	1.00	438.30		438.30	de ✓
24	9	T67881-48070 WEATHERSTRIP, BACK	1.00	441.30		441.30	? X
25	0	T68105-48905 GLASS SUB-ASSY, BACK	1.00	1218.20		1218.20	nee ✓
26	1	T75575-48040 MOULDING, BACK	1.00	51.90		51.90	nee ✓
27	2	T21000-20 SIKI 182010 SIKI TACK GO! (BLA	2.00	108.00		216.00	nee ✓
28	3	T21000-22 SIKI 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00	nee ✓
29	4	T67750-48010 C0 BOARD ASSY, BACK	1.00	578.50		578.50	? X
30	5	T69350-48081 LOCK ASSY, BACK DOOR	1.00	565.20		565.20	? X
31	6	T90975-02071 REAR BOOT LID EMBLEM,	1.00	57.30		57.30	nee ✓
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet				
			Lubrication/Fluid				
			Others				
					Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLP1	Ms Tay Hong Chin Regina (Zheng Hongzhen Regina)	
		Document No. 0	17 King's Close Singapore 268194	
		Document Date 03/05/2021	Mobile: 97717875	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ASU60R	ANTMT E1	20/08/2020	SMU9917G	0	61794	72/DS/SMU9917G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEZB3GH00J005722	8ARZ201029	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
32	7	T75442-48140 PLATE, BACK DOOR	1.00	73.70		73.70
33	8	SPZQ31-13020 Badge Assy, Engine Mark RHS	1.00	17.52		17.52
34	9	T76801-48510 A0 GARNISH SUB-ASSY,	1.00	1055.20		1055.20
35	0	T81551-48431 LENS & BODY, RR	1.00	663.00		663.00
36	1	T81561-48421 LENS & BODY, RR	1.00	663.00		663.00
37	2	T52562-48010 RETAINER, RR BUMPER,	1.00	121.10		121.10
38	3	T52563-48010 RETAINER, RR BUMPER,	1.00	121.10		121.10
39	4	T81581-48251 LENS & BODY, RR	1.00	502.00		502.00
40	5	T81591-48261 LENS & BODY, RR	1.00	502.00		502.00
41	6	T89348-58070 A0 RETAINER, ULTRASONIC	4.00	21.30		85.20
42	7	T89348-58120 RETAINER, ULTRASONIC	4.00	16.00		64.00
43	8	T89341-58060 A0 SENSOR, ULTRASONIC,	2.00	481.90		963.80
44	9	T89997-30100 ANTENNA, ELECTRICAL	1.00	72.00		72.00
45	0	TMKONG-ATGKS GN2 HARRIER GEN 2 AUTO TAILGATE W	1.00	2279.50		2279.50

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	24,720.98
	Please acknowledge receipt of vehicle	Parts 13,655.22	GST 7.00%	1,730.47
		Labour 9,779.40	Less	0.00
		Sublet 1,286.36		
		Lubrication/Fluid 0.00		
		Others 0.00	Amount Due	26,451.45

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLPI1		Ms Tay Hong Chin Regina (Zheng Hongzhen Regina) 17 King's Close Singapore 268194 Mobile: 97717875			
			Document No. 0					
			Document Date 21/05/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	ASU60R	ANTMT E1	20/08/2020	SMU9917G	0	61794	72/DS/SMU9917G	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEZB3GH00J005722		8ARZ201029	60	Thomas Pang W T	04/05/2021	8.00	21/05/2021 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	1	T67005-48340 PANEL SUB-ASSY, BACK M SERIES			1.00	2126.40		✓ bt 2126.40
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 2,126.40	
					Parts 2,126.40		GST 7.00% 148.85	
					Labour 0.00		Less 0.00	
					Sublet 0.00			
					Lubrication/Fluid 0.00			
					Others 0.00		Amount Due 2,275.25	

Company Copy