



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21005409/Utf3n2	
			Date: 21/05/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 7644E		Veh. Inspected	GBE 8083H
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2101389/SYH		Excess (\$)	0.00
Assign From	GRACE TEO		Assign Date	03/05/2021
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350 (M)		c.c	2488
Engine No.	HIDDEN		Year of Reg.	2016
Chassis No.	JN1MC2E26Z0005653		Colour	SILVER
Odometer	87076 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre	195 R15		NEXEN	5 mm
L/H Front Tyre	195 R15		NEXEN	5 mm
R/H Rear Tyre	195 R15		NEXEN	5 mm
L/H Rear Tyre	195 R15		NEXEN	5 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/05/2021		Inspection Date	04/05/2021
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	