


Section A - Accident Details

Registration Number	SHB1838M
Case Reference Number	TAX/05/21/2002
Registration Date	18/12/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	THIA TOH HIN
Type of Accident	Side Swipe
Accident Date and Time	3/5/2021 11:30 AM
Accident Reported Date and Time	3/5/2021 2:04 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110784
Special Instruction to ARC, if any	TP / NTUC - LKK
Prepared Date and Time	3/5/2021 3:57 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$500.00
Total Spray Cost	\$1,854.00	\$600.00
Total Spare Part Cost	\$9,245.95	\$1,607.95
Total Other Cost	\$1,193.76	(\$107.96)
TOTAL COST	\$12,969.71	\$2,600.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	03/05/2021 5:30 PM	03/05/2021 4:26 PM
Signature		
Remarks		L/S, after paint photo. Finalize with Steve

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2105-0198	Invoice Number	
Quotation Date	18.05.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$676.00	\$500.00
Total Labour	\$676.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,854.00	\$600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$593.76	\$445.32
Lump Sum Adjustment by Surveyor	\$0.00	(\$633.28)
Total Other Costs	\$1,193.76	(\$107.96)

X-SVC

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Replace	Repair
		90467-07211	BUMPER CLIPS	0.00	\$2.10	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Not Given
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		89997-30070	ANTENNA,ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given

R
X
√
NEC
X
X
X
X
X
X
X
X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/05/2021

User ID : PohSuan

		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	X	
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	X	
		58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X	
		51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given	X	
		67003-47080	DOOR RR/RH	1.00	\$954.50	25.00	\$715.88	Replace	Replace	√	DD
		69050-47080	DOOR LOCK RR/RH	0.00	\$709.30	0.00	\$0.00	Replace	Not Given	X	
		85710-47120	DOOR REGULATOR MOTOR REAR RH	0.00	\$947.80	0.00	\$0.00	Replace	Check	X	
		69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.80	0.00	\$0.00	Replace	Check	X	
		82153-47300	WIRE RHR, DOOR	0.00	\$280.20	0.00	\$0.00	Replace	Not Given	X	
		68740-12120	DOOR HINGE LOWER RR/RH	0.00	\$90.10	0.00	\$0.00	Replace	Not Given	X	
		68730-12120	DOOR HINGE UPPER RR/RH	0.00	\$90.10	0.00	\$0.00	Replace	Not Given	X	
		68630-47031	CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X	
		69211-74020	DOOR OUTER HANDLE RR/RH	0.00	\$69.80	0.00	\$0.00	Replace	Not Given	X	
		61604-47090	FENDER RR/RH	1.00	\$766.80	25.00	\$575.10	Replace	Replace	√	CRU
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	√	NEC
			STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	√	NEC
		62710-47130	QUARTER GLASS RR/RH	0.00	\$846.50	0.00	\$0.00	Replace	Not Given	X	
			SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	Replace	√	NEC
		65637-47021	FENDER LINE RR/RH	0.00	\$141.30	0.00	\$0.00	Replace	Check	X	
		52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given	X	
		81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Not Given	X	
		62940-16060	DUCT ASSY, QUARTER	0.00	\$70.40	0.00	\$0.00	Replace	Not Given	X	
		42611-47140	WHEEL DISC	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X	
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	
		42602-47060	CAP SUB-ASSY, WHEEL	1.00	\$174.10	25.00	\$130.58	Replace	Replace	√	SCR
		42450-47040	WHEEL HUB REAR	0.00	\$489.40	0.00	\$0.00	Replace	Not Given	X	
		58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Not Given	X	
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	
		75851-47900	MOULDING BODY, RH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given	X	
Total					\$11,873.24		\$1,607.96				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1,607.96 L/S \$2,600/-
+ 500.00
+ 1125.32
3,233.28
-20%
2,586.62