TOTAL



Rico 60 Auto Services Pte Ltd Blk 8 , Kaki Bukit Avenue 4 , #02-24 Premier @ Kaki Bukit Singapore 415875

Email: claims@rico60.com Tel: 6286 6060 Fax : 6286 7060

TO: AIG

Vehicle No : SCK 899 E

Make & Model: BMW 5201

DATE: 3/5/2021

RICO Office Use Only

Parts -%	
SN	
Labour	
Total	
Lump Sum	
ERV	22K

2013

	DATE: 3/3/2021	Constitution of	Lance March		The section of the last last last last	A T
No.	DESCRIPTION - PARTS	QTY	UN	NIT PRICE	PRICE	A
1	BOOT LID 1680,00	1	\$	1,680.00	\$ \sqrt{1,680.00}	DOV
2	BOOT LID LOGO	1	\$	96.00	\$ 39.00 96.00	- LINEC
3	BOOT LID EMBLEM (5201) 64+10	1	\$	97.00	\$64.10 97.00	- V ~
4	BOOT LID REFLECTOR	2	\$	658.00	\$ 1,316.0 0	NDX
5	BOOT LID INNER LOCK	1	\$	552.00	\$ 315.00 552.00	JMV
6	BOOT LID LOCK CATCH	1	\$	66.00	\$ 66.00	NOX
7	BOOT LID WEATHERSTRIP /2.6.30	1	\$	217.90	\$126.80 217.90	TN
8	BOOT LID INNER TRIM	1	\$	255.00	\$ 255.00	NDX
9	BOOT LID SIDE STOPPER	2	\$	90.00	\$ 180.00	NOX
10	BOOT LID DETECTOR	1	\$	321.00	\$280.66321.00	BRV
11	REAR BUMPER 1531-22	1	\$	1,782.00	\$ 1 ,782.00	BRV
12	REAR BUMPER SIDE BRACKET (PLASTIC) 228 - 00	2	\$	114.00	\$ 228.00	BRI
13	REAR BUMPER CENTER BRACKET (CENTER) 150 - 00	1	\$	298.00		BRV
14	REAR BUMPER BOLT COVER	2	\$	59.00		NNX
15	REAR BUMPER REINFORCEMENT 418 60	1	\$	791.00		BTV
16	REAR BUMPER TOWING COVER	1	\$	39.60	\$ 39.60	NA
15.1.5		A	\$ 225	5.45314.00		54/
18	REAR BUMPER SENSOR WIREHARNESS /65 -20	1	\$	698.00	\$ 698.00	CuTV
19	REAR BUMPER SENSOR HOLDER 124-80	4	\$	√31.20	\$ \sqrt{124.80}	NEC
20	REAR BUMPER SENSOR BRACKET	1	\$	120.00	\$ 120.00	NN)
21	REAR BUMPER LOWER GARNISH (CENTER) 109.35	1	\$	195.00	\$ 195.00	BRV
22	REAR BUMPER LOWER GARNISH (SIDE) 106.00	1	\$	258.00	\$ 258.00	BRV
23	REAR BUMPER REFLECTOR 92-40	2	\$46	120 178.00		BRV
24	CONTROL SMART OPENER SENSOR 2 3/4-72	1	\$	384.00	\$ 384.00	}se
	CONTROL SMART OPENER SENSOR 1 414-72	1	\$	526.00	\$ 526.00	5~
26	CONTROL SMART OPENER SENSOR UNIT ECU	1	\$	548.00		BRJ
					ACTION AND ADMINISTRATION OF THE PARTY OF TH	A

						700
27	TAIL LAMP	2	\$550-00754.00	\$	1,508.00	BR
28	TAIL LAMP GARNISH	2	\$ 89.90 125.00	\$	250.00	
29	REAR END PANEL 581.36	1	\$581.36860.00	\$	860.00	DA
30	REAR END PANEL TOP GARNISH 225.00	1	\$ 346.00	\$	346.00	BRI
31	REAR FLOOR TOP BOARD	1	\$ 689.00	\$	689.00	1)
32	REAR FENDER INNER TRIM	2	\$ 458.00	\$	916.00	1)
33	REAR FENDER INNER SHIELD	2	\$ 219.00	\$	438.00	YN
34	REAR EXHAUST PIPE	1	\$ 1,280.00	\$	1,280.00	1/>
35 REAR EXHAUST MOUNTING			\$ 60.00	\$	120.00	1
36	REAR EXHAUST PIPE BRACKET	1	\$ 98.00	\$	98.00	
37	REAR EXHAUST HEAT PLATE (97.90	1	\$ 197 79479.58	\$	479.58	OR
			Ruthir Cod		2 20030	
	9119.8		Subtotal :	\$	19,487.88	-
	Q570 456.00	71-4	Less 5%	\$	974.39	
	8663.82		Parts Total :	\$	18,513.49	
NO.	SPECIAL NETT	QTY	UNIT PRICE		PRICE	
	REAR NUMBER PLATE	1	\$ 50.00	\$	50.00	}
	BOOTLID SEALANT	1	\$ 80.00	\$	80.00	BUN
-	TAIL LAMP CLIP	1	\$ 30.00	\$	30.00	r
	REAR FENDER INNER TRIM CLIPS	1	\$ 50.00	\$3	00 50.00	WG
	REAR FENDER INNER SHIELD CLIPS	1	\$ 50.00	\$	50.00	NH
6	REAR BUMPER CLIP	1	\$ 60.00	\$ 30	00.00	NE
8	REAR END PANEL TOP GARNISH CLIPS	1	\$ 50.00	\$30	10 50.00	NE
9	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 2	0.00 150.00	NE
10	REAR FLOOR PANEL INSULATION SEAL	1	\$ 250.00	\$	250.00	NA
11	REAR FLOOR TOOLS BOX SEALANT	1	\$ 150.00	\$	150.00	FN
12	REAR EXHAUST CHROME HEAD	2	\$ 400.00	\$	800.00	17
					70	
		SPE	CIAL NETT	\$	1,720.00	
	LABOUR				PRICE	
PAI	NEL BEATING, REMOVAL AND REPLACING PARTS		800.00/	\$	1,600.00	
то	SPRAY PAINT AFFECTED AREA		800 . 00	\$	1,600.00	_
TUI	FF COAT		Xan	\$	_200.00	
WIF	RING CHECK		30.00	\$	100.00	
REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR					350.00	
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING 128-10				\$	150.00	
	ANFER BOOTLID MECHANISM		80.00	\$	150.00	_
TIV	WIT LIVE DOOT LID WILDTIN WHOM				0.00	0

CONDUCT WATER LEAKAGE TEST	Xuu	\$	450.00
REMOVE AND REFIX REAR EXHAUST PIPE	150.00-	\$	350.00
TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NNX	\$	_600.00
		-	2080.00
		FOR	
		7.93	
LAB	OUR TOTAL	\$	5,250.00
			10-17-319
Total Par		\$	5,250.00 20,233.49 5,250.00

APPROVED DETAILS NO. OF WORKING DAYS PART BY PART OR LUMP SUM DATE & TIME OF SURVEY SURVEYED BY 97361577 CONTACT NUMBER **FAX NUMBER**

6/5/2021 1430 hrs

Survey

Resurvey on the

Lump sum repair Repair days 6

email teorgrand 4kk auto . com

8663.82 PARTS 170.00 SN LABOUR 2080,00 @2090 2182.21 8731.06

45 8750/2

Terim lui

LKK Auto Consultants hence nouty the Repairer of the following:

. To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- . Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving
- and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.

ACCIDENT STATEMENT

Date of Submission 03/05/2021 14:38 (SGT) Date of Accident 30/04/2021 11:55 (SGT) Exact Location of Accident Singapore Additional Location Information CTE (City) Ang Mo Kio South Flyover After Ang Mo Kio Avenue 1 Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

BMW

Vehicle Registration Number SCK899E

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner POH KIM CHUAN (FU JINQUAN) NRIC No SXXXX673B Email Address ben_poh@hotmail.com Mobile Phone No (Phone) +65-90602520 Alternative Phone No +65-90602520

VEHICLE PARTICULARS

Manufacturer


Model 520i Variant Exact purpose for which vehicle was being used at time of Private use accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Transmission Auto CC 1997

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd Type of Coverage Comprehensive Fleet Policy 5120425715 (CLASSIC) Policy Number Cover Note Number

DRIVER

POH KIM CHUAN (FU JINQUAN) Name of Driver SXXXX673B NRIC No



14/11/1974 Date Of Birth Occupation
Date Of Driving Pass Indoor 18/10/1993 Driving experience 27 YEARS AND 6 MONTHS (Phone) +65-90602520 Mobile Number +65-90602520 Alt, Phone Number ben poh@hotmail.com Email Address BLK 102 RIVERVALE WALK #04-50 Address Address complement 540102 Postcode Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Collision - Head to Rear Type of Accident Clear Weather Conditions Dry Road Surface OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other material or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) No soliciting/offering accident claims assistance? DETAILS OF POLICE ACTION Was the accident reported to the police? Yes Traffic Police Police Station Name (Phone) +65-65470000 Police Station Phone No Alt. Police Station Phone No (Fax) +65-65474900 10 Ubi Avenue 3 Singapore 408865 Police Station Address Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT Refer to Sketch Plan ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded? No DETAILS OF OTHER VEHICLE PROPERTY 1 SMR9272Z Vehicle Registration Number Vehicle Manufacturer

Private car

Accident report SV0M2153000D

Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category

Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	POH KIM CHUAN (FU JINQUAN)
Address	
Address Complement	
Post Code	
Approximate Age Years Old	46
Injuries Sustained	Chest and Neck Pain, 3 Days Medical Leave
Injured person in which vehicle?	SCK899E
Were seat helts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collect/vely the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the 'Purposes')

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholdec's Signature / Date &


Driver's Signature (If driver is not the policyholder) / Date & Time

IDAC KAKI BUKIT (VICOM LTD)

23 KAKI BUKIT AVENUE 4S(415933) Witnessed by Reporting Centre Personnel

Sketch Plan





Declaration

YWe declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

IDAC KAKI BUKIT (VICOM LTD)

23 KAKI BUKIT AVENUE 4S(415933) Witnessed by Reporting Centre Personnel

ON THE STATED DATE AND TIME. I, VEHICLE A (SCK899E) WAS TRAVELLING STRAIGHT ON THE STATED VENUE. WHEN THE FRONT VEHICLE SLOWED DOWN I FOLLOWED SUIT WITHOUT HAVING ANY COLLISION WITH THE FRONT VEHICLE. SUDDENLY I FELT A HUGE IMPACT FROM THE REAR PORTION OF MY VEHICLE. AFTER I ALIGHTED I THEN REALISE THAT IS VEHICLE B (SMR9272Z) THAT HAD COLLIDED ONTO MY VEHICLE.

VEHICLE A: SCK899E

VEHICLE B: SMR9272Z

MOTORCAR (Rear)

÷.

NAC	-INC	ltern	CON	AC	Qh
1137		Rear Number Plate			-
1 1.3,8	The state of the s	Rear Number Plate Base			_
1139		Rear Number Plate Garnish		_	
1140		Reaf Number Plate Lamp			
1141		Rear Bumper	BR	V	
1142		Rear Bumper Upper	BR	1	
1143		Rear Bumper Lower	Die	~	
1144	VSUEGO.	Rear Bumper Side (lower)	BR	V	-
1145	993034	Rear Bumper Tow Cover	BR	V	-
1146				-	-
		Rear Bumper Clips		-	-
1147		Rear Bumper Bracket	BR	V	3
1148	993068	Rear Bumper Side Retainer	-	_	_
1149	993045	Rear Bumper Reinforcement	BT	V	-
1150	992970	Rear Bumper Beam	_	-	-
1151	993077	Rear Bumper Sponge	-	-	-
1153	003040	Rear Bumper Damper Rear Bumper Protector	-	-	-
1154		Rear Bumper Pad	-	+-	+
1155	993030	Rear Bumper Moulding	-	-	+
1156			10 p	1	1
1157		Rear Bumper Reflector	BR	V	19
1157	_		1	1	+
1159	_		136	Y	2
1160	-	Rear End Panel Top Garnish		17	+
1161		Rear End Panel Inner Trim	BR	+	+
1162		Boot Compartment Inner Trim	-	+	+
1163		Rear LH Taillamp	BB	17	+
		Rear LH Taillamp Carnish	BR	V	+
1165		Rear LH Taillamp Panel	1000	1	1
1166	995110	Rear RH Taillamp	BR	1.7	+
1167	7 993853	Rear RH Taillamp Garnish	BR	17	+
1168		Rear RH Taillamp Panel	nk.	1	+
1169		Rear Apron Panel	-	+-	+
1170		Bootlid	DD	1	+
117		B Bootlid Emblem	NE	-	10
1173		Bootlid Handle	IVEC	T	t
117:		Bootlid Moulding	+	+	+
117		Bootlid Reflector	-	+	+
117		2 Bootlid Lamp LH	-	+	+
1170	6 997899	Bootlid Lamp RH	-	+	+
117			1 40	V	-
1171	8 99037	Bootlid Lock Bootlid Rubber Waathership Bootlid Hinge	TA	V	+
1175	990383	2 Bootlid Hinge	1111	Ť	+
1180	0 99387	7 Bootlid Spoiler	13	1	+
118		Tailgate	-	+	+
1183		8 Tailgate Emblem	-	+	+
118		Tailgate Outer Handle	-	+	+
118-		O Tailgate Moulding	-	-	1
118		5 Tailgate Garnish		1	+
118		8 Tailgate Reflector	-	-	+
118		9 Tailgate Lamp	1	+	-
118		6 Tailgate Protector		1	+
118		6 Tailgate Wiper Arm		-	1
119	0 99467	7 Tailgate Wiper Blade	1	-	1
119		9 Tailgate Wiper Nozzle	1	+	+
119		5 Tailgate Wiper Motor	1	-	+
119		2 Tailgate Glass.	-	+	+
-			-	-	-
119		6 Tailgate Glass Rubber		-	-
119		4 Tailgate Glass Moulding			-
119	6 99460	7 Tailgate Glass Sealant			
119	7 99462	9 Tailgate Look			
119		Tailgate Rubber			
119		Tailgate Hinge			
120		4 Tailgate Damper		1	1
		3 Tailgate Inner Board	_	-	-

		Vehicle Nos - SCK	CON	100	-
VAC			CON	AC	77
202 .5	93784	Spare Tyre Board		-	_
203 9	94328	Spare Tyre Panel		-	_
204 5	95065	Spare Tyre		-	_
	94326	Spare Tyre Lock Screw		-	_
206 9	93787	Spare Tyre Cover		-	_
207 9	95323	Triangle Breakdown Sign		-	_
	90507	CD Changer Assy			_
		Antenna			_
1210	990534	Centre Exhaust Pipe Assy -			
1211	000532	Centre Exhaust Mounting			
1212	002264	Rear Exhaust Pipe			
1212	002267	Rear Exhaust Chrome Pipe			_
1213	003361	Rear Exhaust Mounting			-
1215	003358	Rear Exhaust Heat Shield	DD	1	
1216	005223	Rear LH Chassis Member	-		
1217	993165	Rear RH Chassis Member			
		Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
		Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Pender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover	-		
1227	995065	Rear LH Tyre	_		_
1228	993456	Rear RH Fender	-	-	_
1229	993450	Rear RH Fender Protector	-	\vdash	-
1230	993420	Rear RH Fender Inner Panel	-	\rightarrow	_
		Rear RH Fender Inner Trim	-	-	_
	993415	Rear RH Fender Inner Garnish	-	-	-
		Rear RH Fender Inner Shield	-	\vdash	_
1234	993622	Rear RH Mudflap	-	-	_
1235	993934	Rear RH Wheel Rim	-	\vdash	-
		Rear RH Rim Cover		\vdash	
1237	995065	Rear RH Tyre Rear Fender Extension Panel LH	-	\Box	
		Rear Fender Extension Panel RH	-	1	-
		Rear Fender Inner Top Garnish	-		21
		Rear Fender 1/4 Glass .			
1242	993073	Rear Fender 1/4 Glass Rubber	1		
1243		Rear Fender 1/4 Glass Sealant	1		
1244		Rear Windscreen Glass			13
	993976	Rear Windscreen Rubber	1		1
1246	993961	Rear Windscreen Moulding		1	12
1247	993955	Rear Windscreen Sealant			1
1248	994729	Third Brake Light			3
1249	993385	Rear Fender Air Grille	1		100
1250	992167	Fuel Lid	-	-	1
1251	992168	Fuel Neck	-	-	18
1252	992179	Fuel Tank		1	19
1253	992184	Fuel Tank Bracket	-	1	A.V
1254		Fuel Tank Float	-	+	133
319322		Sticker	-	1	18
	BOXTLIA	detection	BR		28
	Rever	se sen sor wire her ness	cui	V	8
	Resser	se senson holder	NE		14
	CHI	Smart opener Smax	SL		13
	V.IV.	n Ecu	BR		10
			1		13
			-	+	100
			-	-	1
	-		-	+	1
	-		-	+	1
-					

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	(minic ye vitanoù anda) ao dato
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	6738
Vehicle No.:	SCK899E
Vehicle to be Exported:	No
Intended Deregistration Date:	03 May 2021
Vehicle Make:	B.M.W.
Vehicle Model:	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	A9430433N20B20B
Chassis No.:	WBAXG12080DX53052
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$42,008.00
Original Registration Date:	28 Mar 2013
First Registration Date:	28 Mar 2013
Transfer Count:	2
Actual ARF Paid: Intended PARF Rebate Details	\$45,812.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Mar 2023
PARF Rebate Amount: Intended COE Rebate Details	\$25,196.00
COE Expiry Date:	27 Mar 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$73,900.00
COE Rebate Amount:	\$14,025.00
Total Rebate Amount:	\$39,221.00

The information contained herein is correct as at 03 May 2021

OK

MV 47,000/2 PV 39,221/2 NV 7779/2

> 100 m line 8/5/2021

Login Sign up

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Glasses Takes Country by Storm

Everyone Over 55 is Rushing to Get These Adjustab VisionFocus

Post an Advertisement Sell it yourself! Advertise it at just

\$68 until it's SOLD!

Toughest Land Rover Discovery Sport



Land Rover Discovery Sport Is One Of The Toughest And Spacious Off Road Vehicle Direct Owner StarAd



Browse by Category

Post an Ad

Ways of Selling

« Back (1 2 3) Next »

▼ 20 results/page Sort by Date Posted

42 vehicles

BMW 520

Model

Advanced Search

Advertiser Login

Price

Depreciation Апу

Reg Date 2013 Eng Cap

Mileage

All

Search Selection

BMW 520

Any

\$68,800

\$16,690 /yr

22-Nov-2013

1.997 cc

128,000 km

Available Luxury



Luxury Free Complimentary 12 Months Warranty From QBE Insurance Company, Facelifted Model With LCI Head Lights, Engine & Gearbox Oil Leak Just.

Free 1 Year Extended Warranty, No Engine/ Gearbox Oil Leak, Full Loan Available. Posted: 08-May-2021 Tags: 2013 BMW 520i, BMW 520i, BMW, 520i

BMW 5 Series 520i

BMW 5 Series 520i

N.A

15-Jan-2013

1.997 cc

Luxury

SOLD

DIRECT OWNER

Well Maintained, Low Mileage, Road Tax Till Jan 2022, Original Condition.

Posted: 17-Apr-2021 Tags: 2013 BMW 520i, BMW 520i, BMW, 520i

BMW 5 Series 520i

23-Jan-2013

1.997 cc

Luxury

SOLD

PREMIUM AD

Nice Bidded Number With Road Tax Till Jan 2022, The Premium Sedan In Superb Condition. One Owner, Full Loan And High Trade In Available, Call For A No Obligation Test Drive And Viewing Today!

Posted: 13-Mar-2021 Tags: 2013 BMW 520i, BMW 520i, BMW, 520i



BMW 5 Series 5201

\$46,800

\$16,460 /yr

31-Jan-2013

1,997 cc

Luxury

Available

\$0 Drive Away And Full Loan Available. Lowest Price 2013 Unit! High Paper-value. Offer Bank Interest Rate From 1.88%, Well Maintained By Previous Owner. Certified 120 Points Test Report With Detailed Chassis Inspection Will Be Provided. Free Servicing At..

Dynamic Motoring

Posted: 07-May-2021 Tags: 2013 BMW 520i, BMW 520i, BMW, 520i



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



BMW 5 Series 5201

\$48,000

\$15,040 Ar

28-Feb-2013

1,997 cc

Luxury Available

New 2K Paintwork & Servicing Upon Sale For This 2nd Owner's Whisky Brown BMW 520L With Luxurious Champagne Leather Upholstery. Road Tax Till 2022, Serviced Regularly, Parked Mostly Under Shelter And 100% Accident Free. Smooth & Healthy Engin...

Posted: 07-May-2021 Tags: 2013 BMW 520I, BMW 520I, BMW, 520I



BMW 5 Series 520i

18-Mar-2013

1,997 cc

Luxury

SOLD

One Owner, Low Mileage, This Vehicle Has Been Inspected By Professional Workshop, Accident-Free, No Need To Repair Anything, Friendly Customer Service, Viewing By Appointment, Welcome To View The Car,

Posted: 20-Apr-2021 Tags: 2013 BMW 520i, BMW 520i, BMW, 520i



BMW 5 Series 520i (OPC)

18-Mar-2013

1,997 cc

Luxury

SOLD

Scarce Findi OPC Unit Super Low Mileage Done At 45,000Km Only! Fully Maintained By Agent PML, 100% Accident Free! 100% No Touch Up From Us Like New! Convertion To Normal Plate To Enjoy The Silky Engine & Gearbox Like New! Come See It Yourself To...

PREMIUM AD

Posted: 16-Mar-2021 Tags: 2013 BMW 520i, BMW 520i, BMW, 520i