Date: 19/05/2021

Your Ref:	
India International Insurance Pte Ltd 64 Cecil Street #04-00 & #05-00 IOB Building Singapore 049711 Attn: Motor Claims Department	
Dear Sir / Madam	
Traffic Accident Along Keppel District Park Involving YP2812E and YP4106Y On 12/06/2020	
We/l, Messers Goldbell Leasing Pte Ltd (ROC No: 199001196N), the regisated at all material times of the above accident. Our/my vehicle was authorized appraiser and we/l based our/my claims on his recommendation for the repair for 02 Days (Strictly on a Without Prejudice Basis).	as surveyed by "India Int'nl"
We / I have ascertained that you were the insurers of the driver of m/vehicle same was involved in the aforesaid accident with our/my m/vehicle — YP2812	
We/I whereby you are the insurers of m/vehicle <u>YP4106Y</u> and the driver/of the negligence of your insured and as a result there of our / my m/vehicle — <u>Yelloss</u> and damage as follows:	
Cost of repairs LOU for pre-repair notice 02 days @ S\$ 140-00 [7545 cc] LOU Fee for 02 days @S\$ 140-00 [7545 cc] Rental Fee Invoice No: GIA / LTA search fee Towing Fee (Cash Sale No:)	2,100-00 280-00 280-00
Total Amount S\$	2,667-45
We/I enclose herewith copies of the supporting documents for vehicle no. YP2 (i) Motor Accident Report & Documents; (ii) Repair Invoices; Kindly look into the matter and let us/me hear from you on the settlement of	
possible.	
Please remit us/me your settlement sum in favor of M/s Liu's Brother Auto Engin the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singa	
Thank you.	}
Yours faithfully,	
The owner of m/vehicle <u>YP2812E</u> Messers Goldbell Leasing Pte Ltd	
cc. Liu's Bro Auto Engineering Workshop	Sign of the second of the seco

Our Ref: YP2812E2006912

Customer

LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793] . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@ymail.com

Invoice/Ref No: YP2812E200612

Final Bill

Name: India International Insurance Pte Ltd

Address Motor Claims Department

64 Cecil Street #04-00 & #05-00

IOB Building

Singapore 049711

Date:

19-05-21

Vehicle No: YP2812E

Model/Make: Mitsubishi Fuso

FM65FM2RDEB

١
١
١

Descriptions Of Parts

Original Quotation / Estimation

Revised Quotation / Cost Of Repair

1	Front Bumper		
2	Bumper Reinforcement	1	
3	Grille	H	
4	Grille Inner	П	
5	Head Lamp	۱	
	To check all wiring & electrical component for proper function Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affec	t€	

\$ 1,828.25 \$ 1,002.50 795.12 455.10 \$ 1,003.20 50.00 580.00

\$ \$

\$

\$

\$

Total Parts & Labour of estimate for damaged vehicle

\$ 6,464.17

750.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS: Two Thousand One Hundred Only



\$ 2,100.00

M/s Liu's Brother Auto Engrg Wks



Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

04 May 2021 / 09:50:57

Receipt Date/Time:

04 May 2021 / 09:50:32

Tax Invoice/Receipt

Receipt No.: ITNET-00000-210504-000711

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - YP4106Y As at 12 Jun 2020/09:35:00 Insurance Co: INDIA INT'L INS PTE LTD 1 Insurance Enquiry - YP4106Y Enquiry Fee 20210504094800497017		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By	12 71		
	426588XXXXXX1485	eNETS (eNETS Credit Card	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.