



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556  
ATTN: CHARLOTTE

Ref: CS/INC21005471/Avf3n2

Date: 16/07/2021

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 7469T	Veh. Inspected	SMU 3208J
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1129520-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	05/05/2021

### 2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ A250	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WDD1771462W032838	Colour	WHITE
Odometer	19365 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	HANKOOK	6 mm
L/H Front Tyre	225/45 R18	HANKOOK	6 mm
R/H Rear Tyre	225/45 R18	HANKOOK	6 mm
L/H Rear Tyre	225/45 R18	HANKOOK	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	24/04/2021	Inspect Date / Time	05/05/2021 ( 11:04 AM )
Survey held at	KINSMEN AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #02-19 AUTOBAY BUILDING SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------